


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 82573

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Himanshu	<b>Inspection Date :</b> 2019-06-13	<b>Location :</b> SEC 21	<b>Inspected By</b>   <b>Manoj Kumar</b>
---------------------------------	--	-----------------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **117** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

✔ Verified Technician

780+ vehicle inspected  
1+ years experience










## Honda Mobilio S I-DTEC, 2015



### VEHICLE INFORMATION

<b>MAKE</b>	HONDA	<b>ENGINE NUMBER</b>	316503
<b>MODEL</b>	MOBILIO	<b>REGISTRATION NO.</b>	DL10CH1799
<b>MFG. DATE</b>	11/2014	<b>VIN/CHASSIS NUMBER</b>	004584
<b>TRIM</b>	S I-DTEC	<b>ODOMETER READING</b>	48554
<b>COLOR</b>	URBAN	<b>INSURANCE EXPIRY</b>	2020-2-3
<b>BODY TYPE</b>	MUV	<b>VEHICLE PASSING</b>	PRIVATE
<b>FUEL TYPE</b>	DIESEL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 <b>FLOOD DAMAGE</b>	NO	 <b>MAJOR ACCIDENT(S)</b>	NO	 <b>SERVICE LOGS AVAILABLE</b>	NO
 <b>TYRE LIFE REMAINING (KM)</b>	10,000	 <b>RC COPY AVAILABLE</b>	ORIGINAL	 <b>BANK HYPOTHECATION</b>	NOT APPLICABLE
 <b>DENT</b>	YES	 <b>INSURANCE COPY AVAILABLE</b>	YES (COMPREHENSIVE)	 <b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






5,58,366




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 <b>Interior</b>	<div style="width: 80%; background-color: #0070C0;"></div>	<b>8 / 10</b>
 <b>Wheel</b>	<div style="width: 60%; background-color: #FFD700;"></div>	<b>6 / 10</b>
 <b>Test Drive</b>	<div style="width: 80%; background-color: #0070C0;"></div>	<b>8 / 10</b>
 <b>Exterior</b>	<div style="width: 60%; background-color: #FFD700;"></div>	<b>6 / 10</b>
 <b>Hood</b>	<div style="width: 80%; background-color: #0070C0;"></div>	<b>8 / 10</b>

#### TOTAL ESTIMATE SPEND 19,800



Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score  **7/10**




**5,58,366**

## INTERIOR

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0

## IMAGES



Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score  **7/10**



**5,58,366**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (YES)	8		0

## IMAGES



## WHEEL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0
TYRES	2	FRONT BOTH SIDE TYRE CRACKING	10000

 IMAGES



 NEED ATTENTION 




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score  **7/10**



**5,58,366**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	MINOR SCRATCHES	300
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	8		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	8		0
LH FRONT DOOR	6	MINOR SCRATCHES	300
LH REAR DOOR	6	MINOR SCRATCHES	300
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	MINOR SCRATCHES AND DENT	500
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	6	MINOR SCRATCHES	300
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	6	MINOR SCRATCHES	300
RH FRONT DOOR	7		0
RH FENDER	6	MINOR DENT AND SCRATCHES	300
BODY RUST	7		0



Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score  **7/10**



**5,58,366**

**EXTERIOR (CONTINUED)**

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FOG LAMPS	0	NA	0
TAIL LIGHT	2	LH SIDE TAIL LIGHT DAMAGE	5000
TRUNK LID/TAIL GATE	3	NEED TO REPAIR	2500


**IMAGES**







 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

minor scratches and minor dent front bumper and rear bumper already painted

Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score



















7/10



5,58,366

IMAGES





Ordered by: Himanshu | Inspected date: 2019-06-13

Order Id: 82573

Overall Score



7/10



5,58,366

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.