



# ECO INSPECTION CERTIFICATE

Premium

Order ID : 81640






121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Radhey	Inspection Date : 2019-06-12	Location : NOIDA	 Inspected By   Verified Technician 113+ vehicle inspected 1+ years experience  Manoj Rawat
------------------------	---------------------------------	---------------------	--

**6/10**

Overall Score

-  Evaluated across 5 segments
-  Covered 121+ checkpoints
-  112 does not need attention
-  1 Owner , 3 Years Vehicle Age
-  No Accidental History










## Maruti Suzuki Celerio VXI, 2016



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	9432200
MODEL	CELERIO	REGISTRATION NO.	HR47C2174
MFG. DATE	03/2016	VIN/CHASSIS NUMBER	292348
TRIM	VXI	ODOMETER READING	103196
COLOR	WHITE	INSURANCE EXPIRY	2019-6-12
BODY TYPE	HATCHBACK	VEHICLE PASSING	COMMERCIAL
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	8,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,71,716**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 27,500



Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score



6/10



2,71,716



## INTERIOR






6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	6	NOT PROPER WORKING HORN NEED TO BE REPAIR	1000
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
SPEAKERS & MUSIC SYSTEM	5	NOT PROPER WORKING NEED TO BE REPAIR	3000
STEERING-MOUNTED CONTROLS	0	NA	0
A/C VENTS & HEATER	5	NOT WORKING NEED TO BE REPAIR	4000



## IMAGES



Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score



6/10



2,71,716


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
SUSPENSION PERFORMANCE	5	SHOCKER DAMAGE NEED TO BE REPAIR	5000
SUSPENSION FRONT SHOCKS	5	SHOCKER LEEAKEGE NEED TO BE REPAIR	5000

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score  **6/10**



**2,71,716**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	7		0
PILLAR	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0



Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score



6/10



2,71,716



## EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	7		0
FOG LAMPS	0	NA	0
FRONT WINDSHIELD	5	MIRROR BROKEN NEED TO BE BEW INSTALL	4000
LH QUARTER PANEL	5	MINIOUR SCRATCHES NEED TO BE REPAIR	1000
REAR BUMPER	0	REAR BUMPER BROKEN NEED TO BE CHANGE	4500





## IMAGES







 **NEED ATTENTION** 



 **DOCUMENTS**





 **DESCRIPTION**

rear bumper is broken need to be change front right and left side suspension leeaage need to be ch

Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score



6/10




















2,71,716

IMAGES







Ordered by: Radhey | Inspected date: 2019-06-12

Order Id: 81640

Overall Score



6/10



2,71,716

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.