


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 80475

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vivek Batra	Inspection Date : 2019-06-12	Location : DELHI	Inspected By  Abu Zafar
-----------------------------	---------------------------------	---------------------	--

## 7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 112 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**  
493+ vehicle inspected  
1+ years experience

## Volkswagen Polo 1.2 TDI HIGHLINE, 2011



### VEHICLE INFORMATION

MAKE	VOLKSWAGEN	ENGINE NUMBER	120391
MODEL	POLO	REGISTRATION NO.	HR26BL3200
MFG. DATE	04/2011	VIN/CHASSIS NUMBER	053393
TRIM	1.2 TDI HIGHLINE	ODOMETER READING	55233
COLOR	DEEPBLACK	INSURANCE EXPIRY	2017-6-12
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	DUPLICATE	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,79,384**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 13,500



Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score  **7/10**



**2,79,384**

## INTERIOR

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
HORN	7		0
HANDBRAKE	7		0
PEDALS	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
DOOR PANEL	3	NEED REPAIR WINDOWS BUTTON	1000
DASHBOARD & INSTRUMENT PANEL	4	NEED DRY CLEAN	1500
SPEAKERS & MUSIC SYSTEM	4	NOT WORKING NEED REPAIR WIRING CONNECTION	1500
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	0	NA	0

## IMAGES



Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score  **7/10**



**2,79,384**

**NEED ATTENTION** ⚠️



**TEST DRIVE**

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

**IMAGES**



Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score  **7/10**




**2,79,384**

## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

## IMAGES



## HOOD



**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0



BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score  **7/10**



**2,79,384**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	MINOR SCRATCHES	1500
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	MINOR SCRATCHES	1500
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	MINOR SCRATCHES	1500
TRUNK LID/TAIL GATE	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	6		0
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0

Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score  **7/10**



**2,79,384**

**EXTERIOR (CONTINUED)**


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	7		0
FRONT BUMPER	4	NEED REPAIR	4000
FOG LAMPS	0	NA	0
TAIL LIGHT	4	RHS BREAKLIGHT NOT WORKING AND BOTH SIDE REVERS LIGHT NOT WORKING NEED REPAIR	1000
LUGGAGE COMPARTMENT LIGHT	0	NA	0


**IMAGES**











 **NEED ATTENTION** 







 DOCUMENTS



 DESCRIPTION

tire change after the 20000km



Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score



7/10



2,79,384






IMAGES











Ordered by: Vivek Batra | Inspected date: 2019-06-12

Order Id: 80475

Overall Score



7/10



2,79,384

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.