

ECO INSPECTION CERTIFICATE

Premium


Order ID : 77334

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sovan Day	Inspection Date : 2019-06-17	Location : BELAGHATA
---------------------------	---------------------------------	-------------------------


6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Rejaul Pailan

- ✓ **Verified Technician**
- 1+ vehicle inspected
- 1+ years experience

Hyundai I20 MAGNA 1.2, 2010



VEHICLE INFORMATION			
MAKE	HYUNDAI	ENGINE NUMBER	LAAM469502
MODEL	I20	REGISTRATION NO.	WB06E0747
MFG. DATE	07/2010	VIN/CHASSIS NUMBER	MALBB51BLAM203366G
TRIM	MAGNA 1.2	ODOMETER READING	36000
COLOR	SILVER	INSURANCE EXPIRY	2019-8-8
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	3,600	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

2,22,148



Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE			TOTAL ESTIMATE SPEND 0				
Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10	0	0	0	0	0
Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Test Drive	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					

Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score



6/10



2,22,148



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (YES)	6	GOOD	0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0



IMAGES



Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score **6/10**



2,22,148

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (YES)	6	GOOD	0
REAR PARKING SENSORS (YES)	6	GOOD	0
REAR VIEW CAMERA (YES)	6	GOOD	0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0

 IMAGES





Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score  **6/10**



2,22,148

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	NO	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH REAR DOOR	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
LH QUARTER PANEL	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
REAR BUMPER	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0

Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score



6/10



2,22,148



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD	0
RH FENDER	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	6	GOOD	0




IMAGES





 DOCUMENTS



 DESCRIPTION

good

Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score















6/10



2,22,148

IMAGES





Ordered by: Sovan Dey | Inspected date: 2019-06-17

Order Id: 77334

Overall Score



6/10



2,22,148

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.