




ECO INSPECTION CERTIFICATE

Premium

Order ID : 83793






121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rajesh	Inspection Date : 2019-06-17	Location : SEC 18	 Inspected By  Manoj Kumar  Verified Technician 793+ vehicle inspected 1+ years experience
------------------------	---------------------------------	----------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

8/10

Overall Score

-  Evaluated across **5** segments
-  Covered **121+** checkpoints
-  **121** does not need attention
-  **1** Owner , **5** Years Vehicle Age
-  No Accidental History










Ford Ecosport TITANIUM 1.5L TI-VCT AT, 2014



VEHICLE INFORMATION

MAKE	FORD	ENGINE NUMBER	17718
MODEL	ECOSPORT	REGISTRATION NO.	HR26CJ0224
MFG. DATE	08/2014	VIN/CHASSIS NUMBER	17718
TRIM	TITANIUM 1.5L TI-VCT AT	ODOMETER READING	50352
COLOR	GREY	INSURANCE EXPIRY	2019-6-17
BODY TYPE	MUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	35,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,69,956




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 1,000



Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score



8/10



6,69,956



INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



IMAGES



Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score **8/10**



6,69,956

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (YES)	8		0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score  **8/10**



6,69,956

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	6	MINOR SCRATCHES	300
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	6	MINOR SCRATCHES	300
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	6	MINOR DENT AND SCRATCHES	400
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score



8/10



6,69,956



EXTERIOR (CONTINUED)




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0




IMAGES





 DOCUMENTS



 DESCRIPTION

minor scratches and minor dent

Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score









8/10



6,69,956

IMAGES





Ordered by: Rajesh | Inspected date: 2019-06-17

Order Id: 83793

Overall Score



8/10



6,69,956

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.