

ECO INSPECTION CERTIFICATE

Premium

Order ID : 84542

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ever Cars	Inspection Date : 2019-06-23	Location : HYDRABAD	Inspected By Verified Technician 170+ vehicle inspected 1+ years experience
----------------------------------	--	-------------------------------	--

10/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

Toyota Innova Crysta 2.8 GX AT 7 STR, 2017



VEHICLE INFORMATION			
MAKE	TOYOTA	ENGINE NUMBER	IGDA079134
MODEL	INNOVA CRYSTA	REGISTRATION NO.	TS12EF0707
MFG. DATE	03/2017	VIN/CHASSIS NUMBER	MBJJA8EM5005066230317
TRIM	2.8 GX AT 7 STR	ODOMETER READING	29745
COLOR	SUPER WHITE	INSURANCE EXPIRY	2019-3-12
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	29,745	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO

orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

16,78,418

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
Wheel	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
Test Drive	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
Exterior	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
Hood	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10

TOTAL ESTIMATE SPEND 0

0

 Interior

0

 Wheel

0

 Test Drive

0

 Exterior

0

 Hood

Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score **10/10**



16,78,418

INTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	10		0
PEDALS	10		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION (YES)	9		0
ODOMETER	10		0
POWER WINDOWS (YES)	10		0
HAZARD LIGHT	10		0

IMAGES



Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score 10/10



16,78,418

TEST DRIVE

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	9		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0
CRUISE CONTROL (YES)	10		0
REAR PARKING SENSORS (YES)	9		0
REAR VIEW CAMERA (YES)	10		0

IMAGES



WHEEL

10/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	10		0
SPARE TYRE (YES)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	9		0

 IMAGES

 HOOD

 10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	10		0
BRAKE FLUID LEVEL	9		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	9		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES


Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score  **10/10**



16,78,418

 **EXTERIOR**

 **10/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9		0
FRONT BUMPER	10		0
HEAD LIGHTS	10		0
GRILLE	10		0
TURN SIGNAL	10		0
FOG LAMPS	10		0
HOOD	10		0
PILLAR	10		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	9		0
LH FENDER	10		0
LH FRONT DOOR	10		0
LH REAR DOOR	9		0
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	9		0
REAR BUMPER	10		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	9		0

Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score **10/10**



16,78,418

EXTERIOR (CONTINUED)

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES



DESCRIPTION

good

Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score  10/10



16,78,418

 IMAGES



Ordered by: Ever cars | Inspected date: 2019-06-23

Order Id: 84542

Overall Score  10/10



16,78,418

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.