

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 84103

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
Vikas Madan

Inspection Date :  
2019-06-19

Location :  
SEC 45

8/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Manoj Kumar

- ✓ Verified Technician
- 816+ vehicle inspected
- 1+ years experience

## Maruti Suzuki Ertiga Zdi+ Shvs, 2016



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	222184
MODEL	ERTIGA	REGISTRATION NO.	HR26CV0151
MFG. DATE	02/2016	VIN/CHASSIS NUMBER	374682
TRIM	ZDI+ SHVS	ODOMETER READING	69601
COLOR	WHITE	INSURANCE EXPIRY	2019-6-19
BODY TYPE	MUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	32,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**6,89,818**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 3,500



Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score



8/10



6,89,818



## INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



## IMAGES



Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score  **8/10**



**6,89,818**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score



8/10



6,89,818

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	MINOR DENT	500
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	6	MINOR DENT	1500
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	MINOR DENT	500
RH RUNNING BOARD	7		0
RH REAR DOOR	6	MINOR DENT	500
RH FRONT DOOR	7		0

Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score



8/10



6,89,818



## EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8	CAR FULL PAINTED	0
LICENSE PLATE	2	NEED TO REPLACE	500



## IMAGES






NEED ATTENTION



DOCUMENTS



DESCRIPTION

car fully painted minor dent all tyres already replaced



Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score



8/10



6,89,818

IMAGES





Ordered by: vikas Madan | Inspected date: 2019-06-19

Order Id: 84103

Overall Score



8/10



6,89,818

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.