

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 83686

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SUMEET GROVER	Inspection Date : 2019-06-20	Location : DELHI
-------------------------------	---------------------------------	---------------------

## 8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**

**Charanpreet Singh**

✓ **Verified Technician**  
91+ vehicle inspected  
1+ years experience

## Maruti Suzuki Swift Dzire VDI, 2017



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	NOT SHOWN
MODEL	SWIFT DZIRE	REGISTRATION NO.	DL1CX2392
MFG. DATE	09/2017	VIN/CHASSIS NUMBER	69750
TRIM	VDI	ODOMETER READING	71215
COLOR	WHITE	INSURANCE EXPIRY	2019-4-14
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**5,54,005**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score



8/10



5,54,005



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	7		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	8		0
NAVIGATION (YES)	8		0
ODOMETER	7		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	7		0



## IMAGES



Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score  **8/10**





**5,54,005**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	7		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	7		0
RADIATOR	8		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	8		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score



8/10



5,54,005



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	7		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	7		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	8		0
LH FENDER	7		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	9		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	9		0
RH REAR DOOR	7		0

Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score



8/10



5,54,005



## EXTERIOR (CONTINUED)





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	7		0
PAINT CONDITION	8		0



## IMAGES





## DOCUMENTS

Registration No: DL 1CX2392		Registration Date: 03-Sep-2017	
Chassis No:	MA3C2F03SH1****	Engine No:	D13A-31****
Owner Name:	JYOTI		
Vehicle Class:	Motor Car(LMV)	Fuel:	DIESEL
Maker / Model:	MARUTI SUZUKI INDIA LTD / MARUTI SUZUKI VDI AMT		
Fitness/Regn Upto:	01-Sep-2022	Insurance Upto:	01-Sep-2019
MV Tax upto:	LTT	PUC Upto:	
Emission norms:	BHARAT STAGE IV	RC Status:	ACTIVE
Financier's Name:	ICICI BANK LTD		



## DESCRIPTION

good



Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score




8/10


















5,54,005

IMAGES



Registration No:	DL1CX2392	Registration Date:	03-Sep-2017
Chassis No:	MA3C2F3334H1**10	Engine No:	D13A-21**17
Owner Name:	JHOTI		
Vehicle Class:	Motor Car(MV)	Fuel:	DIESEL
Maker / Model:	MARUTI SUZUKI INDIA LTD / MARUTI SUZUKI VEDAS		
Fitness Regn Upto:	01-Sep-2022	Insurance Upto:	01-Sep-2019
MI Tax upto:	LTT	PUC upto:	
Emission norm:	BHARAT STAGE IV	RC Status:	ACTIVE
Financier's Name:	KOIC BANK LTD		

click here to see CERSAI details



Ordered by: SUMEET GROVER | Inspected date: 2019-06-20

Order Id: 83686

Overall Score



8/10



5,54,005



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.