


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 85572

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : JAVED ALAM SHAIKH	Inspection Date : 2019-06-26	Location : GRANT ROAD	Inspected By  Sagar Chavan
-----------------------------------	---------------------------------	--------------------------	---

6/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

290+ vehicle inspected

1+ years experience

## Bajaj Dominar 400 ABS, 2017



### VEHICLE INFORMATION

<b>MAKE</b>	BAJAJ	<b>ENGINE NUMBER</b>	
<b>MODEL</b>	DOMINAR	<b>REGISTRATION NO.</b>	MH48AS9298
<b>YEAR</b>	2017	<b>VIN/CHASSIS NUMBER</b>	MD2A67KY9HCL06522
<b>TRIM</b>	400 ABS	<b>ODOMETER READING</b>	13047
<b>COLOR</b>	TWILIGHT P	<b>INSURANCE EXPIRY</b>	2019-5-8
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	38,000	<b>RC COPY AVAILABLE</b>	DUPLICATE	<b>BANK HYPOTHECATION</b>	NOT APPLICABLE
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,37,927




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Tyre</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
<b>Control</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
<b>Light</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
<b>Oil</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
<b>Chassis</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
<b>Stand</b>	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score



6/10



1,37,927

## TYRE




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	NORMAL WEAR & TEAR	0
REAR TYRE CONDITION & AIR PRESSURE	6	NORMAL WEAR & TEAR	0
WHEEL SPOKES FRONT	6	NO DAMAGE	0
WHEEL SPOKES REAR	6	NO DAMAGE	0
WHEEL RIM FRONT	6	NO DAMAGE	0
WHEEL RIM REAR	6	NO DAMAGE	0
WHEEL BEARINGS FRONT	6	WORKING CONDITION	0
WHEEL BEARINGS REAR	6	WORKING CONDITION	0
WHEEL SEALS FRONT	6	NO DAMAGE	0
WHEEL SEALS REAR	6	NO DAMAGE	0
BRAKE FUNCTION FRONT	6	WORKING CONDITION	0
BRAKE FUNCTION REAR	6	WORKING CONDITION	0
BRAKES CONDITION FRONT	6	WORKING CONDITION	0
BRAKES CONDITION REAR	6	WORKING CONDITION	0

## IMAGES





Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score **6/10**



**1,37,927**

## STAND

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	NOT AVAILABLE	0
CENTRE STAND RETENTION	6	NOT AVAILABLE	0
SIDE STAND CONDITION	6	GOOD CONDITION	0
SIDE STAND RETENTION	6	WORKING CONDITION	0

## IMAGES






## CONTROL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	6	GOOD CONDITION	0
PIVOTS	6	NO DAMAGE	0
CABLES CONDITION	6	GOOD CONDITION	0
CABLES ROUTING	6	NO DAMAGE	0
HOSES CONDITION	6	GOOD CONDITION	0
HOSES ROUTING	6	NO DAMAGE	0
THROTTLE OPERATION	6	WORKING CONDITION	0

## IMAGES





## OIL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	MAXIMUM	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (YES)	6	MAXIMUM	0
LEVELS - COOLANT (YES)	6	MAXIMUM	0
LEVELS - FUEL	6	MINIMUM	0
LEAKS - ENGINE OIL	6	NO LEAK FOUND	0
LEAKS - GEAR OIL	6	NO LEAK FOUND	0
LEAKS - HYDRAULIC FLUID	6	NO LEAK FOUND	0
LEAKS - COOLANT	6	NO LEAK FOUND	0
LEAKS - FUEL	6	NO LEAK FOUND	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score



6/10



1,37,927


## LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	GOOD CONDITION	0
BATTERY VENT TUBE	6	NO DAMAGE	0
HEADLAMP CONDITION	6	GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	6	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	WORKING CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	6	WORKING CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	6	WORKING CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	6	WORKING CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	6	WORKING CONDITION	0
SWITCHES OPERATION	6	WORKING CONDITION	0
MIRRORS CONDITION	6	GOOD CONDITION	0
MIRRORS AIM	6	CORRECT	0
LENSES & REFLECTORS CONDITION	6	GOOD CONDITION	0
WIRING CONDITION	6	GOOD CONDITION	0
WIRING ROUTING	6	NO DAMAGE	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score



6/10



1,37,927



## CHASSIS




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	6	NO DAMAGE	0
FRAME SWINGARM BUSHINGS	6	NO DAMAGE	0
SUSPENSION FRONT FORKS LEFT	6	WORKING CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	WORKING CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	MONO SUSPENSION AVAILABLE	0
SUSPENSION REAR SHOCKS RIGHT	6	MONO SUSPENSION AVAILABLE	0
CHAIN/BELT TENSION	6	PROPER TENSION	0
CHAIN/BELT LUBRICATION	6	PROPERLY LUBRICATED	0
CHAIN/BELT SPROCKETS	6	NO DAMAGE	0
FASTENERS THREADED	6	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	6	GOOD CONDITION	0
ENGINE	6	GOOD PERFORMANCE	0
TRANSMISSION	6	SMOOTHLY TRANSFER	0



## IMAGES





Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score




6/10



1,37,927



DOCUMENTS



DESCRIPTION

good condition bike

Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score




6/10



1,37,927

IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-06-26

Order Id: 85572

Overall Score



6/10



1,37,927

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.