


ECO INSPECTION CERTIFICATE

Premium

Order ID : 89367

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Yags	Inspection Date : 2019-07-02	Location : DELHI	Inspected By  Anil Rana
----------------------	---------------------------------	---------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History










✔ **Verified Technician**

378+ vehicle inspected
1+ years experience

Audi A3 35 TDI PREMIUM PLUS + SUNROOF, 2015



VEHICLE INFORMATION			
MAKE	AUDI	ENGINE NUMBER	02658
MODEL	A3	REGISTRATION NO.	DL2CAT4859
MFG. DATE	07/2014	VIN/CHASSIS NUMBER	00526
TRIM	35 TDI PREMIUM PLUS + SUNROOF	ODOMETER READING	58102
COLOR	GLACIER WHITE	INSURANCE EXPIRY	2019-7-2
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

Orange Book Value Not Available





ECO SCORE & REPAIR COST ESTIMATE


ECO SCORE


 Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Wheel	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Test Drive	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Exterior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Hood	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10


TOTAL ESTIMATE SPEND 2,500




 Interior

 Wheel

 Test Drive

 Exterior

 Hood

Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score



7/10



Orange Book Value Not Available



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0



IMAGES



Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score **7/10**



Orange Book Value Not Available

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	7		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	6		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score  **7/10**



Orange Book Value Not Available

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0

Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score **7/10**




Orange Book Value Not Available

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (SUN ROOF)	7		0
PAINT CONDITION	7		0
HEAD LIGHTS	5	RIGHT SIDE NOT WORKING NEED TO REPAIR	2500

IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

good condition

Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score








7/10



Orange Book Value Not Available

IMAGES





Ordered by: Yags | Inspected date: 2019-07-02

Order Id: 89367

Overall Score



7/10



Orange Book Value Not Available

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.