

ECO INSPECTION CERTIFICATE

Premium

Order ID : 91879

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
WAHEED

Inspection Date :
2019-07-09

Location :
PUNE

7/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Ameya Aranke

- ✓ Verified Technician
- 126+ vehicle inspected
- 1+ years experience

Maruti Suzuki Ertiga VDI SHVS, 2017



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	5462605
MODEL	ERTIGA	REGISTRATION NO.	MH12PQ1579
MFG. DATE	06/2017	VIN/CHASSIS NUMBER	MA3FLEB1S00473588
TRIM	VDI SHVS	ODOMETER READING	59654
COLOR	SILVER	INSURANCE EXPIRY	2019-2-19
BODY TYPE	STATION WAGON	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

7,87,300




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score **7/10**




7,87,300

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD HINGES	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD MOVE	0
DASHBOARD & INSTRUMENT PANEL	7	WORKING	0
HORN	7	WORKING	0
SPEAKERS & MUSIC SYSTEM	7	GOOD SOUND	0
HANDBRAKE	7	PROPER HOLD	0
STEERING-MOUNTED CONTROLS	7	WORKING	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	WORKING	0
A/C VENTS & HEATER	7	GOOD COOL	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	WORKING	0
POWER WINDOWS (YES)	7	WORKING	0
HAZARD LIGHT	7	WORKING	0

IMAGES



Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score **7/10**





7,87,300

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	WORKING	0
IGNITION SYSTEM	7	WORKING	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	NO SHOCKS	0
SUSPENSION REAR SHOCKS	7	NO SHOCKS	0
TRANSMISSION ENGAGE	7	GOOD ENGAGE	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD TREAD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAX	0
ENGINE OIL	7	MAX	0
COOLANT LEVEL	7	MAX	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	NO RUSTY	0
EXHAUST SYSTEM	7	NO SMOKE	0

 IMAGES



Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score  **7/10**



7,87,300

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	SCRATCH ON IT	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	7	WORKING	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	NO SPACE	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0

Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score **7/10**



7,87,300

EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	NO RUST	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0

IMAGES



DOCUMENTS



DESCRIPTION

Good condition

Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score





7/10



7,87,300

IMAGES (34)





Ordered by: WAHEED | Inspected date: 2019-07-09

Order Id: 91879

Overall Score



7/10



7,87,300

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.