


ECO INSPECTION CERTIFICATE

Premium

Order ID : 83052

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Atul Gupta	Inspection Date : 2019-07-16	Location : THANE WEST	Inspected By  Verified Technician 282+ vehicle inspected 1+ years experience
-----------------------------------	--	---------------------------------	---

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 2 Owners , 8 Years Vehicle Age
- ✓ No Accidental History










Mahindra Xylo E4 ABS BS IV, 2011



VEHICLE INFORMATION

MAKE	MAHINDRA	ENGINE NUMBER	
MODEL	XYLO	REGISTRATION NO.	MH05AX0152
MFG. DATE	01/2011	VIN/CHASSIS NUMBER	MA1YA2BVNB2A14965
TRIM	E4 ABS BS IV	ODOMETER READING	62711
COLOR	BROWN	INSURANCE EXPIRY	2019-4-2
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	5,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,32,733




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: atul Gupta | Inspected date: 2019-07-16

Order Id: 83052

Overall Score



6/10



3,32,733



INTERIOR









6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	ACCEPTABLE CONDITION	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	GOOD WORKING	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD WORKING CONDITION	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	GOOD WORKING	0
HANDBRAKE	6	PROPERLY WORKING	0
PEDALS	6	GOOD WORKING	0
CENTRAL LOCK	6	WORKING GOOD	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD WORKING	0
POWER WINDOWS (YES)	6	WORKING GOOD	0
HAZARD LIGHT	6	WORKING	0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0



IMAGES






TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	SMOOTHLY WORKING	0
BRAKE PERFORMANCE	6	GOOD WORKING	0
CLUTCH PERFORMANCE	6	WORKING GOOD	0
ENGINE NOISE	6	NORMAL NOISE	0
IGNITION SYSTEM	6	PROPERLY WORKING	0
SUSPENSION PERFORMANCE	6	ABSORBING GOOD ROAD SOCKS	0
SUSPENSION FRONT SHOCKS	6	GOOD SUSPENSION	0
SUSPENSION REAR SHOCKS	6	GOOD SUSPENSION	0
TRANSMISSION ENGAGE	6	SMOOTH GEAR ENGAGEMENT	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0




IMAGES



WHEEL


6/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NORMAL WEAR AND TEAR	0
SPARE TYRE (YES)	6	ACCEPTABLE CONDITION	0

 IMAGES

 HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	ACCEPTABLE CONDITION	0
RH APRON	6	ACCEPTABLE CONDITION	0
RADIATOR	6	GOOD WORKING	0
WIRING	6	ACCEPTABLE CONDITION	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM LEVEL	0
ENGINE OIL	6	GOOD VISCOSITY	0
COOLANT LEVEL	6	MAXIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	ACCEPTABLE CONDITION	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	GOOD WORKING	0

 IMAGES




Ordered by: atul Gupta | Inspected date: 2019-07-16

Order Id: 83052

Overall Score



6/10



3,32,733



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	ACCEPTABLE CONDITION	0
FRONT BUMPER	6	GOOD CONDITION	0
HEAD LIGHTS	6	GOOD WORKING	0
GRILLE	6	GOOD CONDITION	0
TURN SIGNAL	6	GOOD WORKING	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD CONDITION	0
LH FENDER	6	GOOD CONDITION	0
LH FRONT DOOR	6	GOOD CONDITION	0
LH REAR DOOR	6	GOOD CONDITION	0
LH RUNNING BOARD	6	GOOD CONDITION	0
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
REAR BUMPER	6	GOOD CONDITION	0
TAIL LIGHT	6	GOOD WORKING	0
TRUNK LID/TAIL GATE	6	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD SPACE	0
RH QUARTER PANEL	6	GOOD CONDITION	0
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0
RH FRONT DOOR	6	GOOD CONDITION	0

Ordered by: atul Gupta | Inspected date: 2019-07-16

Order Id: 83052

Overall Score **6/10**



3,32,733


EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NO RUST FOUND	0
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD CONDITION	0
FOG LAMPS	0	NOT AVAILABLE	0


IMAGES






NEED ATTENTION





DOCUMENTS



DESCRIPTION

good condition car

Ordered by: atul Gupta | Inspected date: 2019-07-16

Order Id: 83052

Overall Score





6/10











3,32,733

IMAGES (82)







Ordered by: atul Gupta | Inspected date: 2019-07-16

Order Id: 83052

Overall Score



6/10



3,32,733

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.