

ECO INSPECTION CERTIFICATE

Premium

Order ID : 95450

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : ZAHEER SHAFIQ SHAIKH	Inspection Date : 2019-07-18	Location : PUNE
--------------------------------------	---------------------------------	--------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **112** does not need attention
- ✔ **1** Owner , **6** Years Vehicle Age
- ✔ No Accidental History

Inspected By



Sharanappa S

✔ **Verified Technician**
11+ vehicle inspected
1+ years experience

Honda Brio VX (O) MT, 2013



VEHICLE INFORMATION

MAKE	HONDA	ENGINE NUMBER	L12B320116
MODEL	BRIO	REGISTRATION NO.	MH12JU8867
MFG. DATE	02/2013	VIN/CHASSIS NUMBER	MAKDD174BDN106198
TRIM	VX (O) MT	ODOMETER READING	74743
COLOR	WHITE	INSURANCE EXPIRY	2020-5-5
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (3RD PARTY)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,09,695




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 14,650



Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-07-18

Order Id: 95450

Overall Score



7/10



3,09,695



INTERIOR








7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	6		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	6	HEATER NOT WORK	1200
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
PEDALS	5	NOT NEED TO REPAIR	0



IMAGES





TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
CLUTCH PERFORMANCE	4	NEED TO AFTER SOME DAYS NORMAL HARD	3000
SUSPENSION PERFORMANCE	4	SUSPENSION NOISE NEED TO CHECK	3200
TRANSMISSION ENGAGE	5	CLUTCH NORMAL HARD	3000



IMAGES



WHEEL


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	6		0

WHEEL ASSEMBLY (STEEL RIM)


7

0

 IMAGES

 HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	8		0
BATTERY	6		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	8		0
BRAKE FLUID LEVEL	3	NEED TO CHANGE	1200

 IMAGES


Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-07-18

Order Id: 95450

Overall Score



7/10



3,09,695

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	8		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7	NA	0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	6		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	6		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	8		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
RH QUARTER PANEL	9		0
RH REAR DOOR	8		0
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	7		0

Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-07-18

Order Id: 95450

Overall Score



7/10



3,09,695



EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	9		0
SIDE VIEW MIRRORS	3	RH MIRROR LOOSE	1200
FUEL LID	5	CAP HOLDER WIRE BROKEN	50
LUGGAGE COMPARTMENT LIGHT	0	NA	0
RH RUNNING BOARD	0	NEED TO DENTING PENTING	1800




IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

vehicle good condition

www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-07-18

Order Id: 95450

Overall Score




7/10



3,09,695

IMAGES (64)





Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-07-18

Order Id: 95450

Overall Score



7/10



3,09,695



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.