


ECO INSPECTION CERTIFICATE

Premium

Order ID : 95259

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sachin Sakure	Inspection Date : 2019-07-18	Location : PUNE	Inspected By  Verified Technician 28+ vehicle inspected 1+ years experience
--------------------------------------	--	---------------------------	--

7/10

Overall Score

- ✓ Evaluated across **5** segments
- ✓ Covered **121+** checkpoints
- ✓ **115** does not need attention
- ✓ **1** Owner , **6** Years Vehicle Age
- ✓ No Accidental History

Fiat Punto DYNAMIC 1.3, 2013



VEHICLE INFORMATION			
MAKE	FIAT	ENGINE NUMBER	15847
MODEL	PUNTO	REGISTRATION NO.	MH12JZ7454
MFG. DATE	06/2013	VIN/CHASSIS NUMBER	MCA118B5E07044848KLZ
TRIM	DYNAMIC 1.3	ODOMETER READING	78509
COLOR	RED	INSURANCE EXPIRY	2018-12-13
BODY TYPE	COMPACT SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

2,81,378




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, grey 40%);"></div>	6 / 10
Wheel	<div style="width: 80%; background: linear-gradient(to right, green 80%, grey 20%);"></div>	8 / 10
Test Drive	<div style="width: 80%; background: linear-gradient(to right, green 80%, grey 20%);"></div>	8 / 10
Exterior	<div style="width: 70%; background: linear-gradient(to right, green 70%, grey 30%);"></div>	7 / 10
Hood	<div style="width: 80%; background: linear-gradient(to right, green 80%, grey 20%);"></div>	8 / 10

TOTAL ESTIMATE SPEND 5,000



Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score **7/10**




2,81,378

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR HINGES	6	OK	0
CARPET & FLOOR MAT	6	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	7	OK	0
HORN	6	OK	0
SPEAKERS & MUSIC SYSTEM	7	OK	0
HANDBRAKE	6	OK	0
PEDALS	7	OK	0
A/C VENTS & HEATER	6	OK	0
CUP HOLDERS	6	OK	0
NAVIGATION (NO)	10		0
ODOMETER	7	OK	0
POWER WINDOWS (YES)	7	OK	0
HAZARD LIGHT	8	OK	0
DOOR PANEL	5	OK	0
STEERING-MOUNTED CONTROLS	4	NOT APP	0
CENTRAL LOCK	5	REMOT NOT OK	5000

IMAGES



Ordered by: Sachin Sakure | Inspected date: 2019-07-18


Order Id: 95259

Overall Score **7/10**



2,81,378

NEED ATTENTION



TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	OK	0
BRAKE PERFORMANCE	7	OK	0
CLUTCH PERFORMANCE	7	OK	0
ENGINE NOISE	7	OK	0
IGNITION SYSTEM	7	OK	0
SUSPENSION PERFORMANCE	7	OK	0
SUSPENSION FRONT SHOCKS	7	SUS O/H	0
TRANSMISSION ENGAGE	7	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
SUSPENSION REAR SHOCKS	5	OK	0

IMAGES



Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score **7/10**




2,81,378

WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	OK	0
SPARE TYRE (YES)	8	OK	0
WHEEL ASSEMBLY (STEEL RIM)	7	OK	0

IMAGES




HOOD

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	OK	0
RH APRON	6	OK	0
RADIATOR	6	OK	0
WIRING	8	OK	0
BATTERY	8	OK	0
BRAKE FLUID LEVEL	8	OK	0
ENGINE OIL	8	OK	0
COOLANT LEVEL	8	OK	0

BRAKE & COOLANT HOSE PIPES	8	OK	0
UNDERCARRIAGE	8	OK	0
EXHAUST SYSTEM	8	OK	0

IMAGES



Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score



7/10



2,81,378

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	OK	0
FRONT BUMPER	7	OK	0
HEAD LIGHTS	8	OK	0
GRILLE	8	OK	0
TURN SIGNAL	7	OK	0
FOG LAMPS	8	OK	0
HOOD	8	OK	0
PILLAR	8	OK	0
FRONT WINDSHIELD	8	OK	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	8	OK	0
LH FRONT DOOR	8	OK	0
LH REAR DOOR	8	OK	0
LH RUNNING BOARD	8	OK	0
LH QUARTER PANEL	7	OK	0
FUEL LID	8	OK	0
REAR WINDSHIELD	8	OK	0
REAR BUMPER	7	OK	0
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	8	OK	0
RH RUNNING BOARD	7	OK	0
RH REAR DOOR	7	OK	0
RH FRONT DOOR	7	OK	0
RH FENDER	8	OK	0

Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score **7/10**



2,81,378






EXTERIOR (CONTINUED)

7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	8	OK	0
ROOF (REGULAR)	7	OK	0
PAINT CONDITION	8	OK	0
LUGGAGE COMPARTMENT LIGHT	0	OK	0
RH QUARTER PANEL	0	OK	0

IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

good

Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score




















7/10



2,81,378

IMAGES (56)





Ordered by: Sachin Sakure | Inspected date: 2019-07-18

Order Id: 95259

Overall Score



7/10



2,81,378

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.