

ECO INSPECTION CERTIFICATE

Premium

Order ID : 93890

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Zabiulla

Inspection Date :
2019-07-17

Location :
BANGALORE

8/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Girish
Sannayarashi

- ✓ Verified Technician
- 73+ vehicle inspected
- 1+ years experience










Honda Activa 3g 110CC, 2016



VEHICLE INFORMATION

MAKE	HONDA	ENGINE NUMBER	JF50ET3509
MODEL	ACTIVA 3G	REGISTRATION NO.	KA40Y5871
YEAR	2016	VIN/CHASSIS NUMBER	ME4JF505FGT508850
TRIM	110CC	ODOMETER READING	21829
COLOR	WHITE	INSURANCE EXPIRY	2019-6-10
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

33,068




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre	<div style="width: 80%;"></div>	8 / 10
 Control	<div style="width: 80%;"></div>	8 / 10
 Light	<div style="width: 80%;"></div>	8 / 10
 Oil	<div style="width: 80%;"></div>	8 / 10
 Chassis	<div style="width: 80%;"></div>	8 / 10
 Stand	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 300



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score



8/10



33,068


 TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	10	SPOKES NOT AVAILBLE...	0
WHEEL SPOKES REAR	10	SPIKES NOT AVAILABLE....	0
WHEEL RIM FRONT	8		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	7		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	7		0

 IMAGES



Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score **8/10**



33,068

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

IMAGES



CONTROL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	8		0

Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score



8/10



33,068

IMAGES



OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	8		0
LEVELS - HYDRAULIC FLUID (YES)	8		0
LEVELS - COOLANT (YES)	10	NOT AVAILABLE...	0
LEVELS - FUEL	8		0
LEAKS - ENGINE OIL	8		0
LEAKS - GEAR OIL	8		0
LEAKS - HYDRAULIC FLUID	8		0
LEAKS - COOLANT	10	NOT AVAILABLE....	0
LEAKS - FUEL	8		0

IMAGES



Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score



8/10



33,068

 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	7		0
HEADLAMP CONDITION	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8	NOT AVAILABLE...	300
MIRRORS AIM	10	MIRRORS NOT AVAILABLE...	0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

 IMAGES



Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score



8/10



33,068



CHASSIS





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	8		0



IMAGES



Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score




8/10



33,068



DOCUMENTS



DESCRIPTION

good condition vehicle... insurance lapsed...

Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score




8/10



33,068

IMAGES (23)



REG NO: KA40Y 5871 FORM 23A (See Rule 48)

REG DATE	: 15/06/19	O SL NO	: 01
CHASSIS NO	: MEA-F02F978-8850	MFR	: HONDA
ENGINE NO	: JFS0ET3206F03	CLASS	: M/CYCLE
OWNER NAME	: JABULLUKHAN	COLOR	: WHITE
SWD OF	: MAHABOOB S/B		
ADDRESS	: NEAR HADINA SCHOOL ROAD BAGEPALLI TOWN CHIKKABALLAPURA DIST #6 207		
MODEL	: ACTIVA 4G ISVC 110FI		
BODY	: UNDERE	NO OF CYL	: 1
WHEEL BASE	: 1160	WHEEL WT	: 112
MFG DATE	: 06/2015	SEATING	: 2
FUEL	: PETROL	STROKE/PR	: 110
REG'D UPTO	: 15/08/2021	CC	: 110
TAX UPTO	: LTT		

Registering Authority
CHIKKABALLAPURA

Ordered by: Zabiulla | Inspected date: 2019-07-17

Order Id: 93890

Overall Score



8/10



33,068

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.