

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 95750

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
Narender .

Inspection Date :  
2019-07-20

Location :  
ISLAMPUR

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Manoj Kumar

- ✓ Verified Technician
- 904+ vehicle inspected
- 1+ years experience






## Toyota Etios Liva GD SP, 2014



### VEHICLE INFORMATION

MAKE	TOYOTA	ENGINE NUMBER	387516
MODEL	ETIOS LIVA	REGISTRATION NO.	HR72B4100
MFG. DATE	11/2014	VIN/CHASSIS NUMBER	68108
TRIM	GD SP	ODOMETER READING	60130
COLOR	GREY	INSURANCE EXPIRY	2019-7-20
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**3,93,673**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 90%;"></div>	9 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 3,300



Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score



8/10



3,93,673



## INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0
STEERING-MOUNTED CONTROLS	0	NA	0



## IMAGES



Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score  **8/10**




**3,93,673**

## TEST DRIVE

**9/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score  **8/10**



**3,93,673**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8	NA	0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	6	MINOR SCRATCHES	300
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	MINOR DENT AND SCRATCHES	300
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	6	MINOR SCRATCHES	200
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	8		0
RH FRONT DOOR	7		0

Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score



8/10



3,93,673



## EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
LH REAR DOOR	4	NEED TO REPAIR	2500



## IMAGES





**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**

minor scratches and minor dent front bumper and rear bumper already painted rear back door already p

Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score




8/10








3,93,673

 IMAGES (51)







Ordered by: Narender . | Inspected date: 2019-07-20

Order Id: 95750

Overall Score



8/10



3,93,673

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.