

ECO INSPECTION CERTIFICATE

Premium

Order ID : 94104

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Kathie Pm

Inspection Date :
2019-07-17

Location :
CHENNAI

10/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Saravanan R

- ✓ Verified Technician
- 100+ vehicle inspected
- 1+ years experience

Triumph Thunderbird Lt 1700CC, 2016



VEHICLE INFORMATION

MAKE	TRIUMPH	ENGINE NUMBER	C703010
MODEL	THUNDERBIRD LT	REGISTRATION NO.	TN185698
YEAR	2016	VIN/CHASSIS NUMBER	SMTTNB17C7F701528
TRIM	1700CC	ODOMETER READING	8974
COLOR	RED AND BLACK	INSURANCE EXPIRY	2019-7-17
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	YES (BUMPER TO BUMPER)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

12,82,287




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 100%;"></div>	10 / 10
Control	<div style="width: 100%;"></div>	10 / 10
Light	<div style="width: 100%;"></div>	10 / 10
Oil	<div style="width: 100%;"></div>	10 / 10
Chassis	<div style="width: 100%;"></div>	10 / 10
Stand	<div style="width: 100%;"></div>	10 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Kathie pm | Inspected date: 2019-07-17

Order Id: 94104

Overall Score **10/10**



12,82,287

TYRE

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	9	GOOD	0
REAR TYRE CONDITION & AIR PRESSURE	10	GOOD	0
WHEEL SPOKES FRONT	10	GOOD	0
WHEEL SPOKES REAR	10	GOOD	0
WHEEL RIM FRONT	10	GOOD	0
WHEEL RIM REAR	10	GOOD	0
WHEEL BEARINGS FRONT	10	GOOD	0
WHEEL BEARINGS REAR	9	GOOD	0
WHEEL SEALS FRONT	10	GOOD	0
WHEEL SEALS REAR	10	GOOD	0
BRAKE FUNCTION FRONT	9	GOOD	0
BRAKE FUNCTION REAR	10	GOOD	0
BRAKES CONDITION FRONT	10	GOOD	0
BRAKES CONDITION REAR	10	GOOD	0

IMAGES





Ordered by: Kathie pm | Inspected date: 2019-07-17

Order Id: 94104

Overall Score **10/10**



12,82,287

STAND

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	10		0
CENTRE STAND RETENTION	10		0
SIDE STAND CONDITION	10		0
SIDE STAND RETENTION	10		0

IMAGES




CONTROL

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	10	GOOD	0
LEVERS & PEDAL CONDITION	10	GOOD	0
PIVOTS	10	GOOD	0
CABLES CONDITION	10	GOOD	0
CABLES ROUTING	10	GOOD	0
HOSES CONDITION	10	GOOD	0
HOSES ROUTING	10	GOOD	0
THROTTLE OPERATION	10	GOOD	0

IMAGES




OIL

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	10	GOOD	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	10		0
LEVELS - HYDRAULIC FLUID (YES)	10		0
LEVELS - COOLANT (YES)	10		0
LEVELS - FUEL	10		0
LEAKS - ENGINE OIL	10		0
LEAKS - GEAR OIL	10		0
LEAKS - HYDRAULIC FLUID	10		0
LEAKS - COOLANT	10		0
LEAKS - FUEL	10		0

IMAGES



Ordered by: Kathie pm | Inspected date: 2019-07-17

Order Id: 94104

Overall Score **10/10**






12,82,287

LIGHT

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	10	GOOD	0
BATTERY VENT TUBE	10	GOOD	0
HEADLAMP CONDITION	10	GOOD	0
TAILLAMP/BRAKELAMP CONDITION	10	GOOD	0
TAILLAMP/BRAKELAMP OPERATION	10	GOOD	0
TURN SIGNALS OPERATION FRONT LEFT	8	GOOD	0
TURN SIGNALS OPERATION FRONT RIGHT	10	GOOD	0
TURN SIGNALS OPERATION REAR LEFT	9	GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	10	GOOD	0
SWITCHES OPERATION	10	GOOD	0
MIRRORS CONDITION	10	GOOD	0
MIRRORS AIM	10	GOOD	0
LENSES & REFLECTORS CONDITION	10	GOOD	0
WIRING CONDITION	10	GOOD	0
WIRING ROUTING	10	GOOD	0

IMAGES








CHASSIS

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	10		0
FRAME STEERING-HEAD BEARINGS	10		0
FRAME SWINGARM BUSHINGS	10		0
SUSPENSION FRONT FORKS LEFT	10		0
SUSPENSION FRONT FORKS RIGHT	10		0
SUSPENSION REAR SHOCKS LEFT	10		0
SUSPENSION REAR SHOCKS RIGHT	10		0
CHAIN/BELT TENSION	10		0
CHAIN/BELT LUBRICATION	10		0
CHAIN/BELT SPROCKETS	10		0
FASTENERS THREADED	10		0
FASTENERS CLIPS & COTTER PINS	10		0
ENGINE	10		0
TRANSMISSION	10		0



IMAGES



DESCRIPTION

good condition

Ordered by: Kathie pm | Inspected date: 2019-07-17


Order Id: 94104

Overall Score



12,82,287

 IMAGES (29)



Ordered by: Kathie pm | Inspected date: 2019-07-17

Order Id: 94104

Overall Score  10/10



12,82,287

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.