

ECO INSPECTION CERTIFICATE

Premium

Order ID : 94108

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rajesh Gori	Inspection Date : 2019-07-24	Location : MULUND WEST	Inspected By Verified Technician 301+ vehicle inspected 1+ years experience Gaurav Phodkar
------------------------------------	--	----------------------------------	---

6/10

Overall Score

- ✓ Evaluated across **6** segments
- ✓ Covered **121+** checkpoints
- ✓ **119** does not need attention
- ✓ **2** Owners , **6** Years Vehicle Age
- ✓ No Accidental History

Bmw S1000rr Hp4 999CC, 2013



VEHICLE INFORMATION

MAKE	BMW	ENGINE NUMBER	0512E007
MODEL	S1000RR HP4	REGISTRATION NO.	MH02CM7789
YEAR	2013	VIN/CHASSIS NUMBER	WB1050704AZV32997
TRIM	999CC	ODOMETER READING	34958
COLOR	WHITE	INSURANCE EXPIRY	2019-2-3
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	5,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

14,38,435




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 75%;"></div>	6 / 10
Control	<div style="width: 75%;"></div>	6 / 10
Light	<div style="width: 75%;"></div>	6 / 10
Oil	<div style="width: 75%;"></div>	6 / 10
Chassis	<div style="width: 75%;"></div>	6 / 10
Stand	<div style="width: 30%;"></div>	3 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score



6/10



14,38,435






TYRE




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	NORMAL WEAR AND TEAR	0
REAR TYRE CONDITION & AIR PRESSURE	7	NORMAL WEAR AND TEAR	0
WHEEL SPOKES FRONT	7	GOOD CONDITION	0
WHEEL SPOKES REAR	7	GOOD CONDITION	0
WHEEL RIM FRONT	7	GOOD CONDITION	0
WHEEL RIM REAR	7	GOOD CONDITION	0
WHEEL BEARINGS FRONT	6	GOOD WORKING	0
WHEEL BEARINGS REAR	6	GOOD WORKING	0
WHEEL SEALS FRONT	6	NO DAMAGE	0
WHEEL SEALS REAR	6	NO DAMAGE	0
BRAKE FUNCTION FRONT	6	GOOD WORKING	0
BRAKE FUNCTION REAR	6	GOOD WORKING	0
BRAKES CONDITION FRONT	6	GOOD CONDITION	0
BRAKES CONDITION REAR	6	GOOD CONDITION	0

IMAGES





Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score



6/10



14,38,435


STAND




3/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE STAND CONDITION	6	GOOD CONDITION	0
SIDE STAND RETENTION	6	GOOD WORKING	0
CENTRE STAND CONDITION	0	NOT AVAILABLE	0
CENTRE STAND RETENTION	0	NOT AVAILABLE	0

IMAGES



NEED ATTENTION ⚠️



CONTROL




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	7	GOOD WORKING CONDITION	0
PIVOTS	6	GOOD CONDITION	0
CABLES CONDITION	6	GOOD CONDITION	0

CABLES ROUTING	6	NO DAMAGE	0
HOSES CONDITION	6	GOOD CONDITION	0
HOSES ROUTING	6	NO DAMAGE	0
THROTTLE OPERATION	6	PROPERLY WORKING	0

IMAGES






OIL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	MAXIMUM LEVEL	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	6	MAXIMUM LEVEL	0
LEVELS - HYDRAULIC FLUID (YES)	6	MAXIMUM LEVEL	0
LEVELS - COOLANT (YES)	6	MAXIMUM LEVEL	0
LEVELS - FUEL	6	AVERAGE LEVEL	0
LEAKS - ENGINE OIL	6	NO LEAK FOUND	0
LEAKS - GEAR OIL	6	NO LEAK FOUND	0
LEAKS - HYDRAULIC FLUID	6	NO ANY LEAKAGE	0
LEAKS - COOLANT	6	NO LEAKGAGE FOUND	0
LEAKS - FUEL	6	NO LEAK FOUND	0

IMAGES



Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score



6/10



14,38,435




LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	GOOD CONDITION	0
BATTERY VENT TUBE	6	NO DAMAGE	0
HEADLAMP CONDITION	6	GOOD WORKING	0
TAILLAMP/BRAKELAMP CONDITION	6	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	GOOD WORKING	0
TURN SIGNALS OPERATION FRONT LEFT	6	WORKING GOOD	0
TURN SIGNALS OPERATION FRONT RIGHT	6	GOOD WORKING	0
TURN SIGNALS OPERATION REAR LEFT	6	WORKING GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	6	GOOD WORKING	0
SWITCHES OPERATION	6	GOOD WORKING	0
MIRRORS CONDITION	6	GOOD CONDITION	0
MIRRORS AIM	6	NO DAMAGE	0
LENSES & REFLECTORS CONDITION	6	GOOD CONDITION	0
WIRING CONDITION	6	GOOD CONDITION	0
WIRING ROUTING	6	NO DAMAGE	0

IMAGES



Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score **6/10**







14,38,435

CHASSIS

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	6	GOOD WORKING	0
FRAME SWINGARM BUSHINGS	6	ACCEPTABLE CONDITION	0
SUSPENSION FRONT FORKS LEFT	6	GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	MONO SUSPENSION	0
SUSPENSION REAR SHOCKS RIGHT	6	MONO SUSPENSION	0
CHAIN/BELT TENSION	6	GOOD CHAIN TENSION	0
CHAIN/BELT LUBRICATION	6	PROPERLY LUBRICATE	0
CHAIN/BELT SPROCKETS	6	GOOD CONDITION	0
FASTENERS THREADED	6	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	6	GOOD CONDITION	0
ENGINE	6	GOOD WORKING	0
TRANSMISSION	6	SMOOTH GEAR ENGAGEMENT	0

IMAGES



Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score




6/10



14,38,435



DOCUMENTS



DESCRIPTION

good condition bike

Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score




6/10



14,38,435

IMAGES (31)



REGN. NO : MH02CM7789
 REG. DT : 02/02/2012
 CH. NO : 188000234292987
 E NO : 00126267
 NAME : GUNJAN MAROLIA
 SANC OF : ANIL KUMAR
 ADDRESS : BHULE CHIVHSALES ROW HOUSES
 ROAD WASHOLI PUNE 412207
 HPI PLEASE : S1000 DR
 MODEL : SOLO
 NO. OF CYL : 4
 UNLACKER WT : 222
 SEATING C : 2
 WPD DT : 04/09/12
 PETROL
 REG UPDT : 09/02/2017
 TAX UPDT : LTT
 D SNO : 05
 MFCN : BMW AG
 COLOUR : WHITE
 CLASS : MOTO/MP
 Registering Authority PUNE
 Signature



Ordered by: Rajesh gori | Inspected date: 2019-07-24

Order Id: 94108

Overall Score



6/10



14,38,435

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.