


ECO INSPECTION CERTIFICATE

Premium

Order ID : 93532

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Avinash Thakur	Inspection Date : 2019-07-24	Location : SHYAMBAZAR	Inspected By  Verified Technician 83+ vehicle inspected 1+ years experience Ranjit Naskar
---------------------------------------	--	---------------------------------	--

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History










Maruti Suzuki Wagon R Vxi, 2010



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	4892650
MODEL	WAGON R	REGISTRATION NO.	WB26AV1215
MFG. DATE	08/2017	VIN/CHASSIS NUMBER	MA3EWDE1S00C68287
TRIM	VXI	ODOMETER READING	18060
COLOR	MIDNIGHT BLUE	INSURANCE EXPIRY	2019-7-21
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	18,060	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (3RD PARTY)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:




Orange Book Value Not Available

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Avinash Thakur | Inspected date: 2019-07-24

Order Id: 93532

Overall Score



6/10



Orange Book Value Not Available



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0



IMAGES






TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6	GOOD	0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES



 HOOD




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0

 IMAGES





Ordered by: Avinash Thakur | Inspected date: 2019-07-24

Order Id: 93532

Overall Score



6/10



Orange Book Value Not Available



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH REAR DOOR	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
LH QUARTER PANEL	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
REAR BUMPER	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0

Ordered by: Avinash Thakur | Inspected date: 2019-07-24

Order Id: 93532

Overall Score



6/10



Orange Book Value Not Available



EXTERIOR (CONTINUED)







6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD	0
RH FENDER	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	6	GOOD	0






IMAGES





 DOCUMENTS



 DESCRIPTION

good

Ordered by: Avinash Thakur | Inspected date: 2019-07-24

Order Id: 93532

Overall Score




6/10



Orange Book Value Not Available

IMAGES (61)





Ordered by: Avinash Thakur | Inspected date: 2019-07-24

Order Id: 93532

Overall Score



6/10



Orange Book Value Not Available

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.