


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 91678

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

|                              |                                 |                           |   |
|------------------------------|---------------------------------|---------------------------|---|
| Ordered By :<br>Ashok Kannan | Inspection Date :<br>2019-07-09 | Location :<br>HONGASANDRA | Inspected By<br><br>Rajath Singh |
|------------------------------|---------------------------------|---------------------------|---|

## 8/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

- ✓ Verified Technician
- 252+ vehicle inspected
- 1+ years experience

## Hyosung Gt250r 250cc, 2017



### VEHICLE INFORMATION

|           |         |                    |                                     |
|-----------|---------|--------------------|-------------------------------------|
| MAKE      | HYOSUNG | ENGINE NUMBER      | 250163502                           |
| MODEL     | GT250R  | REGISTRATION NO.   | TN67BD0003                          |
| YEAR      | 2017    | VIN/CHASSIS NUMBER | MERGT25R262K00354                   |
| TRIM      | 250CC   | ODOMETER READING   | 3642                                |
| COLOR     | RED     | INSURANCE EXPIRY   | 2019-12-28                          |
| FUEL TYPE | PETROL  | ENGINE SOUND LINK  | <a href="#">LISTEN ENGINE SOUND</a> |

### KEY OBSERVATIONS

|                          |       |                          |                     |                        |     |
|--------------------------|-------|--------------------------|---------------------|------------------------|-----|
| FLOOD DAMAGE             | NO    | MAJOR ACCIDENT(S)        | NO                  | SERVICE LOGS AVAILABLE | NO  |
| TYRE LIFE REMAINING (KM) | 3,642 | RC COPY AVAILABLE        | ORIGINAL            | BANK HYPOTHECATION     | YES |
| DENT                     | NO    | INSURANCE COPY AVAILABLE | YES (COMPREHENSIVE) | BANK NOC               | NO  |



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,96,862**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

|         |                                 |        |
|---------|---------------------------------|--------|
| Tyre    | <div style="width: 80%;"></div> | 8 / 10 |
| Control | <div style="width: 80%;"></div> | 8 / 10 |
| Light   | <div style="width: 80%;"></div> | 8 / 10 |
| Oil     | <div style="width: 80%;"></div> | 8 / 10 |
| Chassis | <div style="width: 80%;"></div> | 8 / 10 |
| Stand   | <div style="width: 90%;"></div> | 9 / 10 |

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score



8/10



2,96,862


## TYRE



8/10

| INSPECTION CHECKPOINTS              | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|-------------------------------------|-------------|------------------|--------------------------|
| FRONT TYRE CONDITION & AIR PRESSURE | 8           |                  | 0                        |
| REAR TYRE CONDITION & AIR PRESSURE  | 8           |                  | 0                        |
| WHEEL SPOKES FRONT                  | 8           |                  | 0                        |
| WHEEL SPOKES REAR                   | 8           |                  | 0                        |
| WHEEL RIM FRONT                     | 8           |                  | 0                        |
| WHEEL RIM REAR                      | 8           |                  | 0                        |
| WHEEL BEARINGS FRONT                | 7           |                  | 0                        |
| WHEEL BEARINGS REAR                 | 8           |                  | 0                        |
| WHEEL SEALS FRONT                   | 8           |                  | 0                        |
| WHEEL SEALS REAR                    | 8           |                  | 0                        |
| BRAKE FUNCTION FRONT                | 8           |                  | 0                        |
| BRAKE FUNCTION REAR                 | 8           |                  | 0                        |
| BRAKES CONDITION FRONT              | 8           |                  | 0                        |
| BRAKES CONDITION REAR               | 8           |                  | 0                        |

## IMAGES





Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score  **8/10**




**2,96,862**

## STAND

**9/10**

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------|-------------|------------------|--------------------------|
| CENTRE STAND CONDITION | 10          | NOT AVAILABLE    | 0                        |
| CENTRE STAND RETENTION | 8           |                  | 0                        |
| SIDE STAND CONDITION   | 8           |                  | 0                        |
| SIDE STAND RETENTION   | 8           |                  | 0                        |

## IMAGES



## CONTROL

**8/10**

| INSPECTION CHECKPOINTS   | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|--------------------------|-------------|------------------|--------------------------|
| HANDLEBARS CONDITION     | 8           |                  | 0                        |
| LEVERS & PEDAL CONDITION | 8           |                  | 0                        |
| PIVOTS                   | 8           |                  | 0                        |
| CABLES CONDITION         | 8           |                  | 0                        |
| CABLES ROUTING           | 8           |                  | 0                        |
| HOSES CONDITION          | 8           |                  | 0                        |
| HOSES ROUTING            | 8           |                  | 0                        |
| THROTTLE OPERATION       | 8           |                  | 0                        |

## IMAGES



## OIL

8/10

| INSPECTION CHECKPOINTS              | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|-------------------------------------|-------------|------------------|--------------------------|
| LEVELS - ENGINE OIL                 | 8           |                  | 0                        |
| LEVELS - GEAR OIL/SHAFT DRIVE (YES) | 8           |                  | 0                        |
| LEVELS - HYDRAULIC FLUID (YES)      | 7           |                  | 0                        |
| LEVELS - COOLANT (YES)              | 7           |                  | 0                        |
| LEVELS - FUEL                       | 8           |                  | 0                        |
| LEAKS - ENGINE OIL                  | 8           |                  | 0                        |
| LEAKS - GEAR OIL                    | 8           |                  | 0                        |
| LEAKS - HYDRAULIC FLUID             | 8           |                  | 0                        |
| LEAKS - COOLANT                     | 8           |                  | 0                        |
| LEAKS - FUEL                        | 7           |                  | 0                        |

## IMAGES





Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score



8/10



2,96,862



**LIGHT**



8/10

| INSPECTION CHECKPOINTS             | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------------------|-------------|------------------|--------------------------|
| BATTERY CONDITION                  | 8           |                  | 0                        |
| BATTERY VENT TUBE                  | 8           |                  | 0                        |
| HEADLAMP CONDITION                 | 8           |                  | 0                        |
| TAILLAMP/BRAKELAMP CONDITION       | 8           |                  | 0                        |
| TAILLAMP/BRAKELAMP OPERATION       | 8           |                  | 0                        |
| TURN SIGNALS OPERATION FRONT LEFT  | 8           |                  | 0                        |
| TURN SIGNALS OPERATION FRONT RIGHT | 7           |                  | 0                        |
| TURN SIGNALS OPERATION REAR LEFT   | 8           |                  | 0                        |
| TURN SIGNALS OPERATION REAR RIGHT  | 8           |                  | 0                        |
| SWITCHES OPERATION                 | 8           |                  | 0                        |
| MIRRORS CONDITION                  | 7           |                  | 0                        |
| MIRRORS AIM                        | 8           |                  | 0                        |
| LENSES & REFLECTORS CONDITION      | 8           |                  | 0                        |
| WIRING CONDITION                   | 8           |                  | 0                        |
| WIRING ROUTING                     | 8           |                  | 0                        |

**IMAGES**



Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score  **8/10**



**2,96,862**

## CHASSIS

**8/10**

| INSPECTION CHECKPOINTS        | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|-------------------------------|-------------|------------------|--------------------------|
| FRAME CONDITION               | 8           |                  | 0                        |
| FRAME STEERING-HEAD BEARINGS  | 7           |                  | 0                        |
| FRAME SWINGARM BUSHINGS       | 8           |                  | 0                        |
| SUSPENSION FRONT FORKS LEFT   | 7           |                  | 0                        |
| SUSPENSION FRONT FORKS RIGHT  | 8           |                  | 0                        |
| SUSPENSION REAR SHOCKS LEFT   | 8           |                  | 0                        |
| SUSPENSION REAR SHOCKS RIGHT  | 7           |                  | 0                        |
| CHAIN/BELT TENSION            | 8           |                  | 0                        |
| CHAIN/BELT LUBRICATION        | 8           |                  | 0                        |
| CHAIN/BELT SPROCKETS          | 8           |                  | 0                        |
| FASTENERS THREADED            | 8           |                  | 0                        |
| FASTENERS CLIPS & COTTER PINS | 8           |                  | 0                        |
| ENGINE                        | 8           |                  | 0                        |
| TRANSMISSION                  | 8           |                  | 0                        |

## IMAGES





Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score






8/10



2,96,862



DOCUMENTS



DESCRIPTION

Front side license plate not available and HP cancellation TN reg bike. good condition bike

Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score




8/10



2,96,862

IMAGES (29)



Ordered by: Ashok Kannan | Inspected date: 2019-07-09

Order Id: 91678

Overall Score



8/10



2,96,862

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.