

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 116168

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
Mr Mitesh

Inspection Date :  
2019-10-19


Location :  
MUMBAI

6/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 0 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Onkar Dhumak

- ✓ Verified Technician
- 8+ vehicle inspected
- 1+ years experience










## Royal Enfield Interceptor 650CC, 2019



### VEHICLE INFORMATION

MAKE	ROYAL ENFIELD	ENGINE NUMBER	NA
MODEL	INTERCEPTOR	REGISTRATION NO.	MH04JY4749
YEAR	2019	VIN/CHASSIS NUMBER	
TRIM	650CC	ODOMETER READING	50679
COLOR	BLACK	INSURANCE EXPIRY	2019-10-8
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

### KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	DUPLICATE	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO









Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,97,557




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Tyre	<div style="width: 75%;"></div>	6 / 10
 Control	<div style="width: 75%;"></div>	6 / 10
 Light	<div style="width: 75%;"></div>	6 / 10
 Oil	<div style="width: 75%;"></div>	6 / 10
 Chassis	<div style="width: 75%;"></div>	6 / 10
 Stand	<div style="width: 75%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. +91- 9650080808 (Toll Free)

-a service by .in

Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score



6/10



1,97,557

## TYRE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	FRONT TYRE IS IN AVERAGE CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	6	REAR TYRE IS IN AVERAGE CONDITION	0
WHEEL SPOKES FRONT	6	FRONT TYRE SPOKES ARE IN AVERAGE CONDITION	0
WHEEL SPOKES REAR	6	REAR TYRE SPOKES ARE IN AVERAGE CONDITION	0
WHEEL RIM FRONT	6	FRONT WHEEL ALLOY RIM IS IN AVERAGE CONDITION	0
WHEEL RIM REAR	6	REAR WHEEL ALLOY RIM IS IN AVERAGE CONDITION	0
WHEEL BEARINGS FRONT	6	FRONT WHEEL BEARING IS WORKING IN AVERAGE CONDITION	0
WHEEL BEARINGS REAR	6	REAR WHEEL BEARING IS WORKING IN AVERAGE CONDITION	0
WHEEL SEALS FRONT	6	WHEEL SEALS FRONT IS IN AVERAGE CONDITION	0
WHEEL SEALS REAR	6	WHEEL SEALS REAR IS IN AVERAGE CONDITION	0
BRAKE FUNCTION FRONT	6	FRONT BRAKE IS WORKING IN AVERAGE CONDITION	0
BRAKE FUNCTION REAR	6	REAR BRAKE IS WORKING IN AVERAGE CONDITION	0
BRAKES CONDITION FRONT	6	FRONT BRAKE IS WORKING IN AVERAGE CONDITION	0
BRAKES CONDITION REAR	6	REAR BRAKE IS WORKING IN AVERAGE CONDITION	0

## IMAGES



Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score




**6/10**



**1,97,557**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	CENTRE STAND IS IN AVERAGE CONDITION	0
CENTRE STAND RETENTION	6	CENTRE STAND IS IN AVERAGE CONDITION	0
SIDE STAND CONDITION	6	SIDE STAND IS IN AVERAGE CONDITION	0
SIDE STAND RETENTION	6	SIDE STAND IS IN AVERAGE CONDITION	0

 IMAGES

 CONTROL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	HANDLE GRIP IS IN AVERAGE CONDITION	0
LEVERS & PEDAL CONDITION	6	LEVERS & PEDAL ARE IN AVERAGE CONDITION	0
PIVOTS	6	PIVOTS ARE IN AVERAGE CONDITION	0
CABLES CONDITION	6	CABLE/TUBE IS IN AVERAGE CONDITION	0
CABLES ROUTING	6	CABLE/TUBE IS IN AVERAGE CONDITION	0
HOSES CONDITION	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
HOSES ROUTING	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
THROTTLE OPERATION	6	THROTTLE IS WORKING IN AVERAGE CONDITION	0

Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score




6/10



1,97,557

## IMAGES



## OIL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	ENGINE OIL IS IN AVERAGE CONDITION	0
LEVELS - HYDRAULIC FLUID (YES)	6	HYDRAULIC FLUID IS IN AVERAGE CONDITION	0
LEVELS - COOLANT (YES)	6	COOLANT FLUID IS IN AVERAGE CONDITION	0
LEVELS - FUEL	6	FUEL IS IN AVERAGE CONDITION	0
LEAKS - ENGINE OIL	6	NO ENGINE OIL LEAKAGE	0
LEAKS - GEAR OIL	6	NO GEAR OIL LEAKAGE	0
LEAKS - HYDRAULIC FLUID	6	NO HYDRAULIC FLUID LEAKAGE	0
LEAKS - COOLANT	6	NO COOLANT LEAKAGE	0
LEAKS - FUEL	6	NO FUEL OIL LEAKAGE	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	N/A		0

## IMAGES





Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score



6/10



1,97,557

 LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	BATTERY IS WORKING IN AVERAGE CONDITION	0
BATTERY VENT TUBE	6	CABLE/TUBE IS IN AVERAGE CONDITION	0
HEADLAMP CONDITION	6	HEAD LIGHTS ARE WORKING IN AVERAGE CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	6	TAILLAMP/BRAKELAMP ARE WORKING IN AVERAGE CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	TAILLAMP/BRAKELAMP ARE WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	6	FRONT LEFT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	6	FRONT RIGHT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	6	REAR LEFT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	6	REAR RIGHT INDICATOR IS WORKING IN AVERAGE CONDITION	0
SWITCHES OPERATION	6	LIGHT/INDICATOR SWITCHES ARE WORKING IN AVERAGE CONDITION	0
MIRRORS CONDITION	6	MIRRORS ARE IN AVERAGE CONDITION	0
MIRRORS AIM	6	MIRRORS ARE IN AVERAGE CONDITION	0
LENSES & REFLECTORS CONDITION	6	LENSES & REFLECTORS ARE IN AVERAGE CONDITION	0
WIRING CONDITION	6	WIRING HARNESS IS IN AVERAGE CONDITION	0
WIRING ROUTING	6	WIRING HARNESS IS IN AVERAGE CONDITION	0



Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score



6/10



1,97,557



## CHASSIS




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	BASE FRAME IS IN AVERAGE CONDITION	0
FRAME STEERING-HEAD BEARINGS	6	STEERING BEARING IS WORKING IN AVERAGE CONDITION	0
FRAME SWINGARM BUSHINGS	6	FRAME SWINGARM BUSHINGS IS IN AVERAGE CONDITION	0
SUSPENSION FRONT FORKS LEFT	6	FRONT LEFT FORK IS IN AVERAGE CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	FRONT RIGHT FORK IS IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	REAR LEFT SHOCK ABSORBER IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	6	REAR RIGHT SHOCK ABSORBER IS WORKING IN AVERAGE CONDITION	0
CHAIN/BELT TENSION	6	DRIVE CHAIN TENSIONER IS IN AVERAGE CONDITION	0
CHAIN/BELT LUBRICATION	6	DRIVE CHAIN AVERAGE LUBRICATION	0
CHAIN/BELT SPROCKETS	6	DRIVE CHAIN SPROCKET IS IN AVERAGE CONDITION	0
FASTENERS THREADED	6	FASTENERS THREADED IS IN AVERAGE CONDITION	0
FASTENERS CLIPS & COTTER PINS	6	FASTENERS CLIPS & COTTER PINS IS IN AVERAGE CONDITION	0
ENGINE	6	ENGINE PERFORMANCE IS IN AVERAGE CONDITION	0
TRANSMISSION	6	TRANSMISSION PERFORMANCE IS IN AVERAGE CONDITION	0



## IMAGES



Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score



6/10



1,97,557



**DESCRIPTION**

Rc book is available with owner but not want to share with vaulater, engine sound not recorded bcoz

Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score







6/10



1,97,557

IMAGES (14)



Ordered by: Mr Mitesh | Inspected date: 2019-10-19

Order Id: 116168

Overall Score



6/10



1,97,557

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.