


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 119388

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Shantanu Bobade	<b>Inspection Date :</b> 2019-11-03	<b>Location :</b> PUNE	<b>Inspected By</b>   <b>Verified Technician</b> 282+ vehicle inspected 1+ years experience <b>Pankaj Patil</b>
--	--	---------------------------	--

**7/10**

**Overall Score**

- ✓ Evaluated across **6** segments
- ✓ Covered **121+** checkpoints
- ✓ **116** does not need attention
- ✓ **1** Owner , **3** Years Vehicle Age
- ✓ No Accidental History

## Hyosung Gt250r 250cc, 2016



### VEHICLE INFORMATION

<b>MAKE</b>	HYOSUNG	<b>ENGINE NUMBER</b>	GT25016186
<b>MODEL</b>	GT250R	<b>REGISTRATION NO.</b>	MH28AU1222
<b>YEAR</b>	2016	<b>VIN/CHASSIS NUMBER</b>	MERGT25R251E01888
<b>TRIM</b>	250CC	<b>ODOMETER READING</b>	7271
<b>COLOR</b>	WHITE	<b>INSURANCE EXPIRY</b>	2019-3-28
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	13,000	<b>RC COPY AVAILABLE</b>	ORIGINAL	<b>BANK HYPOTHECATION</b>	NOT APPLICABLE
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,33,531**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Tyre</b>	<div style="width: 80%;"></div>	<b>8 / 10</b>
<b>Control</b>	<div style="width: 80%;"></div>	<b>8 / 10</b>
<b>Light</b>	<div style="width: 80%;"></div>	<b>8 / 10</b>
<b>Oil</b>	<div style="width: 60%;"></div>	<b>6 / 10</b>
<b>Chassis</b>	<div style="width: 80%;"></div>	<b>8 / 10</b>
<b>Stand</b>	<div style="width: 40%;"></div>	<b>4 / 10</b>

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. +91- 9650080808 (Toll Free)

-a service by .in

Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score  **7/10**



**2,33,531**

## TYRE

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	FRONT TYRE IS IN AVERAGE CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	8	REAR TYRE IS IN GOOD CONDITION	0
WHEEL SPOKES FRONT	8	FRONT TYRE SPOKES ARE IN GOOD CONDITION	0
WHEEL SPOKES REAR	8	REAR TYRE SPOKES ARE IN GOOD CONDITION	0
WHEEL RIM FRONT	8	FRONT WHEEL ALLOY RIM IS IN GOOD CONDITION	0
WHEEL RIM REAR	8	REAR WHEEL ALLOY RIM IS IN GOOD CONDITION	0
WHEEL BEARINGS FRONT	8	FRONT WHEEL BEARING IS WORKING IN GOOD CONDITION	0
WHEEL BEARINGS REAR	8	REAR WHEEL BEARING IS WORKING IN GOOD CONDITION	0
WHEEL SEALS FRONT	8	WHEEL SEALS FRONT IS IN GOOD CONDITION	0
WHEEL SEALS REAR	8	WHEEL SEALS REAR IS IN GOOD CONDITION	0
BRAKE FUNCTION FRONT	8	FRONT BRAKE IS WORKING IN GOOD CONDITION	0
BRAKE FUNCTION REAR	8	REAR BRAKE IS WORKING IN GOOD CONDITION	0
BRAKES CONDITION FRONT	8	FRONT BRAKE IS WORKING IN GOOD CONDITION	0
BRAKES CONDITION REAR	8	REAR BRAKE IS WORKING IN GOOD CONDITION	0

## IMAGES



Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score  **7/10**




**2,33,531**

## STAND

**4/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE STAND CONDITION	8	SIDE STAND IS IN GOOD CONDITION	0
SIDE STAND RETENTION	8	SIDE STAND IS IN GOOD CONDITION	0
CENTRE STAND CONDITION	0	CENTRE STAND NOT AVAILABLE	0
CENTRE STAND RETENTION	0	CENTRE STAND NOT AVAILABLE	0

## IMAGES



## NEED ATTENTION



## CONTROL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8	HANDLE GRIP IS IN GOOD CONDITION	0
LEVERS & PEDAL CONDITION	8	LEVERS & PEDAL ARE IN GOOD CONDITION	0

PIVOTS	8	PIVOTS ARE IN GOOD CONDITION	0
CABLES CONDITION	8	CABLE/TUBE IS IN GOOD CONDITION	0
CABLES ROUTING	8	CABLE/TUBE IS IN GOOD CONDITION	0
HOSES CONDITION	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
HOSES ROUTING	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
THROTTLE OPERATION	8	THROTTLE IS WORKING IN GOOD CONDITION	0

## IMAGES




## OIL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8	ENGINE OIL & LEVEL IS IN GOOD CONDITION	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	8	GEAR OIL & LEVEL IS IN GOOD CONDITION	0
LEVELS - FUEL	8	FUEL & LEVEL IS IN GOOD CONDITION	0
LEAKS - ENGINE OIL	6	NO ENGINE OIL LEAKAGE	0
LEAKS - GEAR OIL	6	NO GEAR OIL LEAKAGE	0
LEAKS - COOLANT	6	NO COOLANT LEAKAGE	0
LEAKS - FUEL	6	NO FUEL OIL LEAKAGE	0
LEVELS - HYDRAULIC FLUID (NO)	N/A		0
LEVELS - COOLANT (NO)	N/A		0
LEAKS - HYDRAULIC FLUID	0	MAJOR HYDRAULIC FLUID LEAKAGE	0

## IMAGES



Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score



7/10



2,33,531

 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8	BATTERY IS WORKING IN GOOD CONDITION	0
BATTERY VENT TUBE	8	CABLE/TUBE IS IN GOOD CONDITION	0
HEADLAMP CONDITION	8	HEAD LIGHTS ARE WORKING IN GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	8	TAILLAMP/BRAKELAMP ARE WORKING IN GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	8	TAILLAMP/BRAKELAMP ARE WORKING IN GOOD CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	8	FRONT LEFT INDICATOR IS WORKING IN GOOD CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	8	FRONT RIGHT INDICATOR IS WORKING IN GOOD CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	8	REAR LEFT INDICATOR IS WORKING IN GOOD CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	8	REAR RIGHT INDICATOR IS WORKING IN GOOD CONDITION	0
SWITCHES OPERATION	8	LIGHT/INDICATOR SWITCHES ARE WORKING IN GOOD CONDITION	0
MIRRORS CONDITION	8	MIRRORS ARE IN GOOD CONDITION	0
MIRRORS AIM	8	MIRRORS ARE IN GOOD CONDITION	0
LENSES & REFLECTORS CONDITION	8	LENSES & REFLECTORS ARE IN GOOD CONDITION	0
WIRING CONDITION	8	WIRING HARNESS IS IN GOOD CONDITION	0
WIRING ROUTING	8	WIRING HARNESS IS IN GOOD CONDITION	0





Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score



7/10



2,33,531

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8	BASE FRAME IS IN GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	8	STEERING BEARING IS WORKING IN GOOD CONDITION	0
FRAME SWINGARM BUSHINGS	8	FRAME SWINGARM BUSHINGS IS IN GOOD CONDITION	0
SUSPENSION FRONT FORKS LEFT	8	FRONT LEFT FORK IS IN GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	8	FRONT RIGHT FORK IS IN GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	8	REAR LEFT SHOCK ABSORBER IS WORKING IN GOOD CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	8	REAR RIGHT SHOCK ABSORBER IS WORKING IN GOOD CONDITION	0
CHAIN/BELT TENSION	8	DRIVE CHAIN TENSIONER IS IN GOOD CONDITION	0
CHAIN/BELT LUBRICATION	6	DRIVE CHAIN AVERAGE LUBRICATION	0
CHAIN/BELT SPROCKETS	8	DRIVE CHAIN SPROCKET IS IN GOOD CONDITION	0
FASTENERS THREADED	8	FASTENERS THREADED IS IN GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	8	FASTENERS CLIPS & COTTER PINS IS IN GOOD CONDITION	0
ENGINE	8	ENGINE PERFORMANCE IS IN GOOD CONDITION	0
TRANSMISSION	8	TRANSMISSION PERFORMANCE IS IN GOOD CONDITION	0

 IMAGES


Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score



7/10



2,33,531



DOCUMENTS



DESCRIPTION

very good condition

Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score




7/10



2,33,531

IMAGES (18)



Ordered by: Shantanu Bobade | Inspected date: 2019-11-03

Order Id: 119388

Overall Score



7/10



2,33,531

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.