


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 121135

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Bassam Khan	Inspection Date : 2019-11-14	Location : MUMBAI	 <p>Inspected By</p> <p><b>Verified Technician</b> 431+ vehicle inspected 1+ years experience</p> <p>Gaurav Phodkar</p>
<p><b>6/10</b></p> <p>Overall Score</p> <ul style="list-style-type: none"> <li>Evaluated across 6 segments</li> <li>Covered 121+ checkpoints</li> <li>117 does not need attention</li> <li>1 Owner, 2 Years Vehicle Age</li> <li>No Accidental History</li> </ul>			

## Benelli Tnt 300 300CC, 2017



### VEHICLE INFORMATION

MAKE	BENELLI	ENGINE NUMBER	25155
MODEL	TNT 300	REGISTRATION NO.	MH01CS6945
YEAR	2017	VIN/CHASSIS NUMBER	MERTN301272C00968
TRIM	300CC	ODOMETER READING	9734
COLOR	WHITE	INSURANCE EXPIRY	2019-9-28
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,52,871**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Tyre	<div style="width: 70%;"></div>	7 / 10
Control	<div style="width: 60%;"></div>	6 / 10
Light	<div style="width: 70%;"></div>	7 / 10
Oil	<div style="width: 60%;"></div>	6 / 10
Chassis	<div style="width: 70%;"></div>	7 / 10
Stand	<div style="width: 30%;"></div>	3 / 10

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. +91- 9650080808 (Toll Free)

-a service by .in

Ordered by: Bassam Khan | Inspected date: 2019-11-14

Order Id: 121135

Overall Score



6/10



2,52,871





## TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	FRONT TYRE IS IN AVERAGE CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	6	REAR TYRE IS IN AVERAGE CONDITION	0
WHEEL SPOKES FRONT	8	FRONT TYRE SPOKES ARE IN GOOD CONDITION	0
WHEEL SPOKES REAR	8	REAR TYRE SPOKES ARE IN GOOD CONDITION	0
WHEEL RIM FRONT	8	FRONT WHEEL ALLOY RIM IS IN GOOD CONDITION	0
WHEEL RIM REAR	8	REAR WHEEL ALLOY RIM IS IN GOOD CONDITION	0
WHEEL BEARINGS FRONT	6	FRONT WHEEL BEARING IS WORKING IN AVERAGE CONDITION	0
WHEEL BEARINGS REAR	6	REAR WHEEL BEARING IS WORKING IN AVERAGE CONDITION	0
WHEEL SEALS FRONT	6	WHEEL SEALS FRONT IS IN AVERAGE CONDITION	0
WHEEL SEALS REAR	6	WHEEL SEALS REAR IS IN AVERAGE CONDITION	0
BRAKE FUNCTION FRONT	8	FRONT BRAKE IS WORKING IN GOOD CONDITION	0
BRAKE FUNCTION REAR	8	REAR BRAKE IS WORKING IN GOOD CONDITION	0
BRAKES CONDITION FRONT	8	FRONT BRAKE IS WORKING IN GOOD CONDITION	0
BRAKES CONDITION REAR	8	REAR BRAKE IS WORKING IN GOOD CONDITION	0

## IMAGES



Ordered by: Bassam Khan | Inspected date: 2019-11-14

Order Id: 121135

Overall Score **6/10**




**2,52,871**

## STAND

**3/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE STAND CONDITION	6	SIDE STAND IS IN AVERAGE CONDITION	0
SIDE STAND RETENTION	6	SIDE STAND IS IN AVERAGE CONDITION	0
CENTRE STAND CONDITION	0	CENTRE STAND NOT AVAILABLE	0
CENTRE STAND RETENTION	0	CENTRE STAND NOT AVAILABLE	0

## IMAGES



## NEED ATTENTION





## CONTROL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	HANDLE GRIP IS IN AVERAGE CONDITION	0
LEVERS & PEDAL CONDITION	6	LEVERS & PEDAL ARE IN AVERAGE CONDITION	0

PIVOTS	6	PIVOTS ARE IN AVERAGE CONDITION	0
CABLES CONDITION	6	CABLE/TUBE IS IN AVERAGE CONDITION	0
CABLES ROUTING	6	CABLE/TUBE IS IN AVERAGE CONDITION	0
HOSES CONDITION	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
HOSES ROUTING	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
THROTTLE OPERATION	8	THROTTLE IS WORKING IN GOOD CONDITION	0

## IMAGES



## OIL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	ENGINE OIL IS IN AVERAGE CONDITION	0
LEVELS - HYDRAULIC FLUID (YES)	8	HYDRAULIC FLUID & LEVEL IS IN GOOD CONDITION	0
LEVELS - COOLANT (YES)	6	COOLANT FLUID IS IN AVERAGE CONDITION	0
LEVELS - FUEL	6	FUEL IS IN AVERAGE CONDITION	0
LEAKS - ENGINE OIL	6	NO ENGINE OIL LEAKAGE	0
LEAKS - HYDRAULIC FLUID	6	NO HYDRAULIC FLUID LEAKAGE	0
LEAKS - COOLANT	6	NO COOLANT LEAKAGE	0
LEAKS - FUEL	6	NO FUEL OIL LEAKAGE	0

LEVELS - GEAR OIL/SHAFT DRIVE (NO)	N/A		0
LEAKS - GEAR OIL	0	MAJOR GEAR OIL LEAKAGE	0

 IMAGES



Ordered by: Bassam Khan | Inspected date: 2019-11-14

Order Id: 121135

Overall Score



6/10



2,52,871

 LIGHT






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8	BATTERY IS WORKING IN GOOD CONDITION	0
BATTERY VENT TUBE	8	CABLE/TUBE IS IN GOOD CONDITION	0
HEADLAMP CONDITION	8	HEAD LIGHTS ARE WORKING IN GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	8	TAILLAMP/BRAKELAMP ARE WORKING IN GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	TAILLAMP/BRAKELAMP ARE WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	6	FRONT LEFT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	6	FRONT RIGHT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	6	REAR LEFT INDICATOR IS WORKING IN AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	6	REAR RIGHT INDICATOR IS WORKING IN AVERAGE CONDITION	0
SWITCHES OPERATION	6	LIGHT/INDICATOR SWITCHES ARE WORKING IN AVERAGE CONDITION	0
MIRRORS CONDITION	6	MIRRORS ARE IN AVERAGE CONDITION	0
MIRRORS AIM	6	MIRRORS ARE IN AVERAGE CONDITION	0
LENSES & REFLECTORS CONDITION	6	LENSES & REFLECTORS ARE IN AVERAGE CONDITION	0
WIRING CONDITION	6	WIRING HARNESS IS IN AVERAGE CONDITION	0
WIRING ROUTING	6	WIRING HARNESS IS IN AVERAGE CONDITION	0



## IMAGES



## CHASSIS



7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	BASE FRAME IS IN AVERAGE CONDITION	0
FRAME STEERING-HEAD BEARINGS	6	STEERING BEARING IS WORKING IN AVERAGE CONDITION	0
FRAME SWINGARM BUSHINGS	6	FRAME SWINGARM BUSHINGS IS IN AVERAGE CONDITION	0
SUSPENSION FRONT FORKS LEFT	6	FRONT LEFT FORK IS IN AVERAGE CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	FRONT RIGHT FORK IS IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	REAR LEFT SHOCK ABSORBER IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	6	REAR RIGHT SHOCK ABSORBER IS WORKING IN AVERAGE CONDITION	0
CHAIN/BELT TENSION	8	DRIVE CHAIN TENSIONER IS IN GOOD CONDITION	0
CHAIN/BELT LUBRICATION	8	DRIVE CHAIN GOOD LUBRICATION	0
CHAIN/BELT SPROCKETS	8	DRIVE CHAIN SPROCKET IS IN GOOD CONDITION	0
FASTENERS THREADED	6	FASTENERS THREADED IS IN AVERAGE CONDITION	0

FASTENERS CLIPS & COTTER PINS	6	FASTENERS CLIPS & COTTER PINS IS IN AVERAGE CONDITION	0
ENGINE	8	ENGINE PERFORMANCE IS IN GOOD CONDITION	0
TRANSMISSION	8	TRANSMISSION PERFORMANCE IS IN GOOD CONDITION	0

## IMAGES



## DOCUMENTS



## DESCRIPTION

good condition bike

Ordered by: Bassam Khan | Inspected date: 2019-11-14

Order Id: 121135

Overall Score






6/10



2,52,871

IMAGES (33)





Ordered by: Bassam Khan | Inspected date: 2019-11-14

Order Id: 121135

Overall Score



6/10



2,52,871



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.