


ECO INSPECTION CERTIFICATE

Premium

Order ID : 126341

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : ZAHEER SHAFIQ SHAIKH	Inspection Date : 2019-12-18	Location : PUNE	Inspected By  Shekhar Mundhe
--------------------------------------	---------------------------------	--------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **116** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

246+ vehicle inspected
1+ years experience





Renault Pulse RxZ Petrol, 2015



VEHICLE INFORMATION

MAKE	RENAULT	ENGINE NUMBER	18172
MODEL	PULSE	REGISTRATION NO.	MH04GU3805
MFG. DATE	01/2013	VIN/CHASSIS NUMBER	02098
TRIM	RXZ PETROL	ODOMETER READING	71726
COLOR	M BLACK	INSURANCE EXPIRY	2019-12-18
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	YES





Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,04,600




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 60%;"></div>	6 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 2,000



Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score



7/10



3,04,600



INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	BOTH DOOR'S PANELS ARE IN GOOD CONDITION	0
DOOR HINGES	8	BOTH DOOR'S HINGES & LATCH ARE WORKING IN GOOD CONDITION	0
CARPET & FLOOR MAT	8	CARPET IS IN GOOD CONDITION	0
SEAT & SEAT BELT	8	SEATS/SEAT COVERS ARE IN GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	DASHBOARD/INSTRUMENT PANEL IS IN GOOD CONDITION	0
HORN	8	HORN SOUND IS IN GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	8	HAND BRAKE IS IN GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	STEERING MOUNTED CONTROLS ARE WORKING IN GOOD CONDITION	0
PEDALS	8	ALL PEDAL'S BOOT IS IN GOOD CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
CUP HOLDERS	6	CUP HOLDERS ARE IN AVERAGE CONDITION	0
ODOMETER	6	ODOMETER IS WORKING IN AVERAGE CONDITION	0
POWER WINDOWS (YES)	6	ALL POWER WINDOWS ARE WORKING IN AVERAGE CONDITION.	0
HAZARD LIGHT	6	HAZARD LIGHT IS WORKING IN AVERAGE CONDITION	0


IN AVERAGE CONDITION

NAVIGATION (NO)

N/A

0

 IMAGES



Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score



7/10



3,04,600



TEST DRIVE




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	STEERING WORKING IS IN AVERAGE CONDITION	0
BRAKE PERFORMANCE	6	BRAKES ARE WORKING IN AVERAGE CONDITION	0
CLUTCH PERFORMANCE	6	CLUTCH IS WORKING IN AVERAGE CONDITION	0
ENGINE NOISE	6	SOMETIMES MINOR NOISE IN ENGINE.	0
IGNITION SYSTEM	6	IGNITION SYSTEM IS WORKING IN AVERAGE CONDITION.	0
SUSPENSION PERFORMANCE	6	SUSPENSION PERFORMANCE IS IN AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	FRONT SUSPENSION IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	REAR SUSPENSION IS WORKING IN AVERAGE CONDITION	0
TRANSMISSION ENGAGE	6	TRANSMISSION IS WORKING IN AVERAGE CONDITION	0
CRUISE CONTROL (NO)	N/A		0
REAR PARKING SENSORS (NO)	N/A		0
REAR VIEW CAMERA (NO)	N/A		0




IMAGES









INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	TIRES ARE IN AVERAGE CONDITION	0
SPARE TYRE (YES)	6	SPARE TYRE IS IN AVERAGE CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	8	WHEEL ASSEMBLY IS IN GOOD CONDITION	0

 IMAGES

 HOOD


8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	LH APRON IS IN GOOD CONDITION	0
RH APRON	8	RH APRON IS IN GOOD CONDITION	0
RADIATOR	8	RADIATOR IS IN GOOD CONDITION	0
WIRING	8	WIRING HARNESS IS IN GOOD CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	8	BRAKE FLUID & LEVEL IS IN GOOD CONDITION	0
ENGINE OIL	8	ENGINE OIL IS IN GOOD CONDITION	0
COOLANT LEVEL	8	COOLANT LEVEL IS IN GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
UNDERCARRIAGE	8	UNDERCARRIAGE IS IN GOOD CONDITION	0
EXHAUST SYSTEM	8	NORMAL SMOKE	0

 IMAGES



Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score  **7/10**



3,04,600

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	LICENSE PLATE IS IN AVERAGE CONDITION.	0
FRONT BUMPER	6	FRONT BUMPER IS IN AVERAGE CONDITION	0
HEAD LIGHTS	6	HEAD LIGHTS ARE WORKING IN AVERAGE CONDITION	0
GRILLE	6	GRILLE IS IN AVERAGE CONDITION	0
TURN SIGNAL	6	INDICATOR IS WORKING IN AVERAGE CONDITION	0
HOOD	6	HOOD IS IN AVERAGE CONDITION	0
PILLAR	6	LH PILLARS ARE IN AVERAGE CONDITION	0
FRONT WINDSHIELD	6	FRONT WINDSHIELD IS IN AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	LH SIDE VIEW MIRROR/ASSY IS IN AVERAGE CONDITION	0
LH FENDER	6	LH FENDER IS IN AVERAGE CONDITION	0
LH FRONT DOOR	6	LH FRONT DOOR IS IN AVERAGE CONDITION	0
LH REAR DOOR	6	LH REAR DOOR IS IN AVERAGE CONDITION	0
LH RUNNING BOARD	6	LH RUNNING BOARD IS IN AVERAGE CONDITION	0
LH QUARTER PANEL	6	LH QUARTER PANEL IS IN AVERAGE CONDITION	0
FUEL LID	6	FUEL LID IS IN AVERAGE CONDITION	0
REAR WINDSHIELD	6	REAR WINDSHIELD IS IN AVERAGE CONDITION	0
REAR BUMPER	6	REAR BUMPER IS IN AVERAGE CONDITION	0

TAIL LIGHT	6	TAIL LIGHT IS WORKING IN AVERAGE CONDITION	0
TRUNK LID/TAIL GATE	6	TRUNK LID IS IN AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	LUGGAGE COMPARTMENT LIGHT IS WORKING IN AVERAGE CONDITION	0
RH QUARTER PANEL	6	RH QUARTER PANEL IS IN AVERAGE CONDITION	0
RH RUNNING BOARD	6	RH RUNNING BOARD IS IN AVERAGE CONDITION	0
RH REAR DOOR	6	RH REAR DOOR IS IN AVERAGE CONDITION	0
RH FRONT DOOR	6	RH FRONT DOOR IS IN AVERAGE CONDITION	0

Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score



7/10



3,04,600



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	RH FENDER IS IN AVERAGE CONDITION	0
BODY RUST	6	BODY RUST 25%-MINOR	0
ROOF (REGULAR)	6	ROOF IS IN AVERAGE CONDITION	0
PAINT CONDITION	6	PAINT IS IN AVERAGE CONDITION	0
FOG LAMPS	4	FOG LAMPS CRACKED-MINOR	2000



IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score





7/10



3,04,600

IMAGES (54)





Ordered by: ZAHEER SHAFIQ SHAIKH | Inspected date: 2019-12-18

Order Id: 126341

Overall Score



7/10



3,04,600



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.