

# ECO INSPECTION REPORT

Premium

Order ID : 9715






ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : SALIMKHAN PATHAN

Inspection Date : 04/04/2017

8/10

Overall Score

-  Evaluated across 6 segments
-  Covered 121+ checkpoints
-  120 does not need attention
-  1 owner , 6 Years Vehicle Age
-  No Accidental History

Inspected By



Abhijit Rathod

 Verified Technician

135+ vehicle inspected

1+ years experience

## Hero Passion Pro 100cc, 2011



### VEHICLE INFORMATION

MAKE	HERO	LOCATION	KHANPUR
MODEL	PASSION PRO	REGISTRATION NO	GJ01 N7552
YEAR	2011	VIN/CHASIS NUMBER	ABCD
TRIM	100CC	KMS RUN	31035
COLOR	BLACK	INSURANCE EXPIRY	2016-4-10
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Value for this vehicle comes to be:

**24,647**




Very Good Condition

### ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

#### ECO SCORE

 Tyre	<div style="width: 80%;"></div>	8 / 10
 Control	<div style="width: 80%;"></div>	8 / 10
 Light	<div style="width: 80%;"></div>	8 / 10
 Oil	<div style="width: 80%;"></div>	8 / 10
 Chassis	<div style="width: 80%;"></div>	8 / 10
 Stand	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score  **8/10**



**24,647**

DOES NOT NEED ATTENTION

NEED ATTENTION

## TYRE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES CONDITION & AIR PRESSURE FRONT	9		0
TYRES CONDITION & AIR PRESSURE REAR	8		0
WHEELS SPOKES FRONT	8		0
WHEELS SPOKES REAR	8		0
WHEELS RIMS FRONT	8		0
WHEELS RIMS REAR	8		0
WHEELS BEARINGS FRONT	8		0
WHEELS BEARINGS REAR	8		0
WHEELS SEALS FRONT	8		0
WHEELS SEALS REAR	8		0
BRAKES FUNCTION FRONT	8		0
BRAKES FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

## STAND

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score



8/10



24,647

DOES NOT NEED ATTENTION

NEED ATTENTION



## CONTROL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	8		0



## OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LEVELS – ENGINE OIL	8		0
LEVELS – GEAR OIL, SHAFT DRIVE	8		0
LEVELS – HYDRAULIC FLUID	8		0
LEVELS – COOLANT	8		0
LEVELS – FUEL	8		0
LEAKS – ENGINE OIL	8		0
LEAKS – GEAR OIL, SHAFT DRIVE	8		0
LEAKS – HYDRAULIC FLUID	8		0
LEAKS – COOLANT	8		0
LEAKS – FUEL	8		0
ENGINE SOUND	0		0

Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score



8/10



24,647

DOES NOT NEED ATTENTION

NEED ATTENTION

 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	8		0
HEADLAMP AIM	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	7		0
WIRING ROUTING	8		0

Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score  **8/10**



**24,647**

DOES NOT NEED ATTENTION

NEED ATTENTION

## CHASSIS

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCK(S) LEFT	8		0
SUSPENSION REAR SHOCK(S) RIGHT	8		0
CHAIN OR BELT TENSION	8		0
CHAIN OR BELT LUBRICATION	8		0
CHAIN OR BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	8		0

## DESCRIPTION

Good vehicle

Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score



8/10




24,647

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



SAMPLE

Ordered by: SALIMKHAN PATHAN | Inspected date: 04/04/2017

Order Id: 9715

Overall Score



8/10



24,647

DOES NOT NEED ATTENTION

NEED ATTENTION



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE

SAMPLE