

# ECO INSPECTION REPORT


Premium

Order ID : 14821

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : Pritpal Singh | Inspection Date : 23/08/2017


## 6/10



**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 110 does not need attention
- ✓ 1 owner , 5 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**

680+ vehicle inspected

1+ years experience

**Sandeep Kumar**

## Nissan Micra Xv Diesel, 2012

VEHICLE INFORMATION			
MAKE	NISSAN	TRANSMISSION TYPE	MANUAL
MODEL	MICRA	REGISTRATION NO	DL
YEAR	2012	VIN/CHASIS NUMBER	017699
TRIM	XV DIESEL	KMS RUN	64064
COLOR	SILVER	INSURANCE EXPIRY	2017-6-2
BODY TYPE	OTHER	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	5,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Value for this vehicle comes to be:






## 4,04,709




Good Condition

## ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

**ECO SCORE**

 Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	<b>7 / 10</b>
 Wheel	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	<b>6 / 10</b>
 Test	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	<b>6 / 10</b>
 Exterior	<div style="width: 70%; background-color: green; height: 10px;"></div>	<b>7 / 10</b>
 Hood	<div style="width: 70%; background-color: green; height: 10px;"></div>	<b>7 / 10</b>

**TOTAL ESTIMATE SPEND 8,500**



Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score **6/10**



**4,04,709**

DOES NOT NEED ATTENTION

NEED ATTENTION

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	7	OK	0
DOOR HINGES	7	OK	0
CARPET & FLOOR MAT	7	OK	0
SEAT & SEAT BELT	7	OK	0
DASHBOARD & INSTRUMENT PANEL	7	OK	0
HORN	7	OK	0
SPEAKERS	7	OK	0
HANDBRAKE	7	OK	0
PEDAL	7	OK	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS AND HEATER	7	OK	0
CUP HOLDER	7	OK	0
SPEEDOMETER/ODOMETER	7	OK	0
POWER WINDOWS (YES)	7	OK	0
HAZARD LIGHTS	7	OK	0
STEERING MOUNTED CONTROLS	0	NA	0
NAVIGATION	0	NA	0

## WHEEL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
SPARE TYRE	6	OK	0
WHEEL ASSEMBLY (STEEL RIM)	7	OK	0
TYRES	5	OK	0

Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score



6/10



4,04,709

DOES NOT NEED ATTENTION

NEED ATTENTION



## TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE PERFORMANCE	7	OK	0
CLUTCH PERFORMANCE	7	OK	0
ENGINE NOISE	7	OK	0
IGNITION SYSTEM	7	OK	0
SUSPENSION PERFORMANCE	7	OK	0
SUSPENSION FRONT SHOCKS	7	OK	0
SUSPENSION REAR SHOCKS	7	OK	0
TRANSMISSION ENGAGE	7	OK	0
STEERING PERFORMANCE	1	NA	0
CRUISE CONTROL	0	NA	0
REAR PARKING SENSORS	2	NA	0
REAR VIEW CAMERA	0	NA	0



## HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	7	OK	0
RH APRON	7	OK	0
RADIATOR	7	OK	0
WIRING	7	OK	0
BATTERY	7	OK	0
BRAKE FLUID LEVEL	7	OK	0
COOLANT LEVEL	7	OK	0
BRAKE & COOLANT HOSE PIPES	7	OK	0

Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score  **6/10**



**4,04,709**

DOES NOT NEED ATTENTION

NEED ATTENTION

## HOOD (CONTINUED)

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
UNDERCARRIAGE	7	OK	0
EXHAUST SYSTEM	7	OK	0
ENGINE SOUND	0		0
ENGINE OIL	3	SERVICE REQUIRED	8500

## EXTERIOR

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	7	OK	0
FRONT BUMPER	6	GOOD BUT REPAINT, NEEDS ADJUSTMENT	0
HEAD LIGHTS	7	OK	0
GRILLE	7	OK	0
TURN SIGNAL	7	OK	0
HOOD	7	GOOD BUT REPAINT	0
PILLAR	7	OK	0
FRONT WINDSHIELD	7	OK	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	7	GOOD BUT REPAINT	0
LH FRONT DOOR	7	GOOD BUT REPAINT	0
LH REAR DOOR	7	GOOD BUT REPAINT	0
LH RUNNING BOARD	7	OK	0
LH QUARTER PANEL	7	GOOD BUT REPAINT	0

Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score  **6/10**



**4,04,709**

DOES NOT NEED ATTENTION

NEED ATTENTION

## EXTERIOR (CONTINUED)

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FUEL LID	7	OK	0
REAR WINDSHIELD	7	OK	0
REAR BUMPER	7	GOOD BUT REPAINT	0
TAIL LIGHT	7	OK	0
TRUNK LID/TAIL GATE	7	OK	0
RH QUARTER PANEL	7	GOOD BUT REPAINT	0
RH RUNNING BOARD	7	OK	0
RH REAR DOOR	7	OK	0
RH FRONT DOOR	7	OK	0
RH FENDER	7	GOOD BUT REPAINT	0
BODY RUST	8	NO	0
ROOF (REGULAR)	7	OK	0
PAINT CONDITION	7	OK	0
FOG LAMPS	0	NA	0
LUGGAGE COMPARTMENT LIGHT	0	NA	0

## DESCRIPTION

good condition

Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score



6/10





4,04,709

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES





## ECO INSPECTION REPORT

Premium

Ordered by: Pritpal Singh | Inspected date: 23/08/2017

Order Id: 14821

Overall Score



6/10



4,04,709

DOES NOT NEED ATTENTION

NEED ATTENTION



### DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

