

ECO INSPECTION CERTIFICATE

Premium

Order ID : 31197

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
First Name

Inspection Date :
2018-11-29

Valid Till :
2019-03-02

Inspected By

7/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History



Sanjeev
Agarwal

- ✓ Verified Technician
- 198+ vehicle inspected
- 1+ years experience

Bajaj Ct 100 100CC, 2016



VEHICLE INFORMATION

MAKE	BAJAJ	LOCATION	NALLASOPARA
MODEL	CT 100	REGISTRATION NO.	MH11CC3616
YEAR	2016	VIN/CHASIS NUMBER	03422
TRIM	100CC	KMS RUN	14587
COLOR	RED	INSURANCE EXPIRY	2018-10-18
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	5,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

26,303




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	7/10
Control	7/10
Light	7/10
Oil	8/10
Chassis	7/10
Stand	7/10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score **7/10**




26,303

TYRE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7		0
REAR TYRE CONDITION & AIR PRESSURE	7		0
WHEEL SPOKES FRONT	7		0
WHEEL SPOKES REAR	7		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	7		0
WHEEL BEARINGS FRONT	7		0
WHEEL BEARINGS REAR	7		0
WHEEL SEALS FRONT	7		0
WHEEL SEALS REAR	7		0
BRAKE FUNCTION FRONT	7		0
BRAKE FUNCTION REAR	7		0
BRAKES CONDITION FRONT	7		0
BRAKES CONDITION REAR	7		0

IMAGES



Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score **7/10**



26,303

STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7		0
CENTRE STAND RETENTION	7		0
SIDE STAND CONDITION	7		0
SIDE STAND RETENTION	7		0

IMAGES



CONTROL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7		0
LEVERS & PEDAL CONDITION	7		0
PIVOTS	7		0
CABLES CONDITION	7		0
CABLES ROUTING	7		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	7		0

Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score **7/10**



26,303

IMAGES





OIL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	7		0
LEAKS - ENGINE OIL	7		0
LEAKS - GEAR OIL	7		0
LEAKS - HYDRAULIC FLUID	7		0
LEAKS - COOLANT	7		0
LEAKS - FUEL	7		0

IMAGES



Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score **7/10**



26,303

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7		0
BATTERY VENT TUBE	7		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	7		0
TAILLAMP/BRAKELAMP OPERATION	7		0
TURN SIGNALS OPERATION FRONT LEFT	7		0
TURN SIGNALS OPERATION FRONT RIGHT	7		0
TURN SIGNALS OPERATION REAR LEFT	7		0
TURN SIGNALS OPERATION REAR RIGHT	7		0
SWITCHES OPERATION	7		0
MIRRORS CONDITION	7		0
MIRRORS AIM	7		0
LENSES & REFLECTORS CONDITION	7		0
WIRING CONDITION	7		0
WIRING ROUTING	7		0

IMAGES



Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score **7/10**





26,303

CHASSIS

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	7		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	7		0
SUSPENSION FRONT FORKS RIGHT	7		0
SUSPENSION REAR SHOCKS LEFT	7		0
SUSPENSION REAR SHOCKS RIGHT	7		0
CHAIN/BELT TENSION	7		0
CHAIN/BELT LUBRICATION	7		0
CHAIN/BELT SPROCKETS	7		0
FASTENERS THREADED	7		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0

IMAGES



Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score



7/10



26,303



DOCUMENTS



DESCRIPTION

Good condition

Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score









7/10



26,303

IMAGES



Ordered by: First Name | Inspected date: 2018-11-29

Order Id: 31197

Overall Score



7/10



26,303

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.