



ECO INSPECTION CERTIFICATE

Premium

Order ID : 54271

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Raju Mulekar	Inspection Date : 2019-04-03	Location : POWAI	 Inspected By  Sanmesh Latke Verified Technician 94+ vehicle inspected 1+ years experience
<h2>8/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> Evaluated across 5 segments Covered 121+ checkpoints 121 does not need attention 1 Owner , 3 Years Vehicle Age No Accidental History 	

Bmw X3 XDRIVE 20D XLINE, 2016



VEHICLE INFORMATION

MAKE	BMW	ENGINE NUMBER	7092
MODEL	X3	REGISTRATION NO.	MH43AX6007
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	71133
TRIM	XDRIVE 20D XLINE	ODOMETER READING	20000
COLOR	WHITE	INSURANCE EXPIRY	2019-4-17
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:




Orange Book Value Not Available

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score



8/10



Orange Book Value Not Available



INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9	OK	0
DOOR HINGES	8	OK	0
CARPET & FLOOR MAT	8	OK	0
SEAT & SEAT BELT	8	OK	0
DASHBOARD & INSTRUMENT PANEL	8	OK	0
HORN	8	OK	0
SPEAKERS & MUSIC SYSTEM	8	OK	0
HANDBRAKE	8	OK	0
STEERING-MOUNTED CONTROLS	8	OK	0
PEDALS	8	OK	0
CENTRAL LOCK	8	OK	0
A/C VENTS & HEATER	8	OK	0
CUP HOLDERS	8	OK	0
NAVIGATION (YES)	8	OK	0
ODOMETER	8	OK	0
POWER WINDOWS (YES)	8	OK	0
HAZARD LIGHT	8	OK	0



IMAGES



Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score **8/10**



Orange Book Value Not Available

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	OK	0
BRAKE PERFORMANCE	8	OK	0
CLUTCH PERFORMANCE	8	OK	0
ENGINE NOISE	8	OK	0
IGNITION SYSTEM	8	OK	0
SUSPENSION PERFORMANCE	8	OK	0
SUSPENSION FRONT SHOCKS	9	OK	0
SUSPENSION REAR SHOCKS	8	OK	0
TRANSMISSION ENGAGE	8	OK	0
CRUISE CONTROL (YES)	8	OK	0
REAR PARKING SENSORS (YES)	8	OK	0
REAR VIEW CAMERA (YES)	8	OK	0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	OK	0
SPARE TYRE (YES)	8	OK	0
WHEEL ASSEMBLY (ALLOY RIM)	8	OK	0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	OK	0
RH APRON	8	OK	0
RADIATOR	8	OK	0
WIRING	8	OK	0
BATTERY	8	OK	0
BRAKE FLUID LEVEL	8	OK	0
ENGINE OIL	8	OK	0
COOLANT LEVEL	8	OK	0
BRAKE & COOLANT HOSE PIPES	8	OK	0
UNDERCARRIAGE	8	OK	0
EXHAUST SYSTEM	8	OK	0

 IMAGES



Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score



8/10



Orange Book Value Not Available

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	OK	0
FRONT BUMPER	8	OK	0
HEAD LIGHTS	8	OK	0
GRILLE	8	OK	0
TURN SIGNAL	8	OK	0
FOG LAMPS	8	OK	0
HOOD	8	OK	0
PILLAR	8	OK	0
FRONT WINDSHIELD	8	OK	0
SIDE VIEW MIRRORS	8	OK	0
LH FENDER	8	OK	0
LH FRONT DOOR	8	OK	0
LH REAR DOOR	8	OK	0
LH RUNNING BOARD	8	OK	0
LH QUARTER PANEL	8	OK	0
FUEL LID	8	OK	0
REAR WINDSHIELD	8	OK	0
REAR BUMPER	9	OK	0
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	8	OK	0
LUGGAGE COMPARTMENT LIGHT	8	OK	0
RH QUARTER PANEL	8	OK	0
RH RUNNING BOARD	8	OK	0
RH REAR DOOR	8	OK	0

Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score



8/10



Orange Book Value Not Available



EXTERIOR (CONTINUED)





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	OK	0
RH FENDER	8	OK	0
BODY RUST	8	OK	0
ROOF (REGULAR)	8	OK	0
PAINT CONDITION	8	OK	0



IMAGES



DESCRIPTION

car in best condition.

Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score




8/10



Orange Book Value Not Available

IMAGES



Ordered by: Raju Mulekar | Inspected date: 2019-04-03

Order Id: 54271

Overall Score



8/10



Orange Book Value Not Available

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.