


ECO INSPECTION CERTIFICATE

Premium

Order ID : 64732

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Zia Kamil Raie	Inspection Date : 2019-04-24	Location : LAMINTAN ROAD	Inspected By  Manjeet Singh
--------------------------------	---------------------------------	-----------------------------	--

7/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **118** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

28+ vehicle inspected
1+ years experience










Aprilia Sr 150 150CC, 2018



VEHICLE INFORMATION

MAKE	APRILIA	ENGINE NUMBER	M911M30433
MODEL	SR 150	REGISTRATION NO.	MH01DC8653
YEAR	2018	VIN/CHASSIS NUMBER	MET0001AAVA042415
TRIM	150CC	ODOMETER READING	45017
COLOR	OTHER	INSURANCE EXPIRY	2019-3-12
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (PARTIAL)
 TYRE LIFE REMAINING (KM)	22,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:







65,030




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Control	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Light	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Oil	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Chassis	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Stand	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score



7/10



65,030


TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD	0
WHEEL SPOKES FRONT	7	GOOD	0
WHEEL SPOKES REAR	7	GOOD	0
WHEEL RIM FRONT	7	GOOD	0
WHEEL RIM REAR	7	GOOD	0
WHEEL BEARINGS FRONT	7	GOOD CONDITION	0
WHEEL BEARINGS REAR	7	GOOD CONDITION	0
WHEEL SEALS FRONT	7	GOOD CONDITION	0
WHEEL SEALS REAR	7	GOOD	0
BRAKE FUNCTION FRONT	7	GOOD	0
BRAKE FUNCTION REAR	7	GOOD	0
BRAKES CONDITION FRONT	7	GOOD	0
BRAKES CONDITION REAR	7	GOOD	0

IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score



7/10



65,030

STAND



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	GOOD	0
CENTRE STAND RETENTION	7	GOOD	0
SIDE STAND CONDITION	7	GOOD	0
SIDE STAND RETENTION	7	WORKING CANDITION	0

IMAGES



CONTROL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD	0
LEVERS & PEDAL CONDITION	7	NO DAIMAGE	0
CABLES CONDITION	7	WORKING	0
CABLES ROUTING	6	WORKING	0
HOSES CONDITION	6	WORKING	0
HOSES ROUTING	7	WORKING	0
THROTTLE OPERATION	6	WORKING	0
PIVOTS	0	NOT AVILABAL	0

IMAGES





OIL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	MAXIMAM LEVEL	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (YES)	7	MAXIMAM LEVEL	0
LEVELS - COOLANT (NO)	10		0
LEAKS - ENGINE OIL	7	MAXIMAM LIVEL	0
LEAKS - GEAR OIL	6	NO	0
LEAKS - HYDRAULIC FLUID	7	NO	0
LEAKS - FUEL	7	NO	0
LEVELS - FUEL	5	MINEMAM LEVEL	0
LEAKS - COOLANT	0	NO	0

IMAGES



Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score



7/10



65,030


LIGHT



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	GOOD	0
BATTERY VENT TUBE	6	GOOD	0
HEADLAMP CONDITION	7	GOOD	0
TAILLAMP/BRAKELAMP CONDITION	7	WORKING	0
TAILLAMP/BRAKELAMP OPERATION	7	WORKING CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	7	GOOD	0
TURN SIGNALS OPERATION FRONT RIGHT	7	GOOD	0
TURN SIGNALS OPERATION REAR LEFT	7	GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	7	GOOD	0
SWITCHES OPERATION	7	WORKING	0
MIRRORS CONDITION	7	GOOD	0
MIRRORS AIM	7	GOOD	0
LENSES & REFLECTORS CONDITION	7	GOOD	0
WIRING CONDITION	7	GOOD	0
WIRING ROUTING	7	WORKING	0

IMAGES



Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score **7/10**




65,030

CHASSIS

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7	GOOD	0
FRAME STEERING-HEAD BEARINGS	7	GOOD	0
FRAME SWINGARM BUSHINGS	7	GOOD	0
SUSPENSION FRONT FORKS LEFT	7	GOOD	0
SUSPENSION FRONT FORKS RIGHT	7	GOOD	0
SUSPENSION REAR SHOCKS LEFT	7	MONO CANDITION	0
SUSPENSION REAR SHOCKS RIGHT	7	MONO CANDITION	0
CHAIN/BELT TENSION	7	WORKING CONDITION	0
CHAIN/BELT LUBRICATION	7	WORKING CONDITION	0
CHAIN/BELT SPROCKETS	6	WORKING CONDITION	0
FASTENERS THREADED	7	GOOD	0
FASTENERS CLIPS & COTTER PINS	7	GOOD	0
ENGINE	7	WORKING CANDITION	0
TRANSMISSION	7	ACCELERATION	0

IMAGES



Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score




7/10



65,030



DOCUMENTS



DESCRIPTION

good condition bike

Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score




7/10



65,030

IMAGES



Ordered by: Zia Kamil Raie | Inspected date: 2019-04-24

Order Id: 64732

Overall Score



7/10



65,030

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.