


ECO INSPECTION CERTIFICATE

Premium

Order ID : 64788

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Romal	Inspection Date : 2019-04-27	Location : NAGPUR	Inspected By  Shahbaz Sheikh
-----------------------	---------------------------------	----------------------	---

6/10
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 111 does not need attention
- 2 Owners , 14 Years Vehicle Age
- No Accidental History

Verified Technician
45+ vehicle inspected
1+ years experience

Tata Indica DLS, 2005



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	HUZPB1799
MODEL	INDICA	REGISTRATION NO.	MH31CN0807
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	600142HUZPA8855
TRIM	DLS	ODOMETER READING	83443
COLOR	RED	INSURANCE EXPIRY	2010-10-23
BODY TYPE	STATION WAGON	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	1,500	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

76,778




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 25,000



Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score



6/10



76,778



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	6		0
STEERING-MOUNTED CONTROLS	0	NA	5000



IMAGES



Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score **6/10**



76,778

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
ENGINE NOISE	5	NOISY	5000

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score  **6/10**



76,778

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
GRILLE	6		0
TURN SIGNAL	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
FRONT BUMPER	5	SCRATCH	2000
HEAD LIGHTS	4	LEFT LIGHT YELLOW	2500
FOG LAMPS	0	NA	1500

Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score



6/10



76,778



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE VIEW MIRRORS	5	DAMAGE	1000
LH FENDER	5	POOR	2000
LH RUNNING BOARD	5	POOR	2000
RH QUARTER PANEL	5	POOR	2000
RH FENDER	5	POOR	2000



IMAGES



NEED ATTENTION



Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score



6/10



76,778



DESCRIPTION

average condition

Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score



6/10



76,778

IMAGES



Ordered by: romal | Inspected date: 2019-04-27

Order Id: 64788

Overall Score



6/10



76,778

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.