


ECO INSPECTION CERTIFICATE

Premium

Order ID : 68237

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vikas Madan	Inspection Date : 2019-04-27	Location : SEC 45	 <p>Inspected By Manoj Kumar</p> <p>✓ Verified Technician 618+ vehicle inspected 1+ years experience</p>
<p>8/10</p> <p>Overall Score</p>			
<ul style="list-style-type: none"> ✓ Evaluated across 5 segments ✓ Covered 121+ checkpoints ✓ 119 does not need attention ✓ 1 Owner , 7 Years Vehicle Age ✓ No Accidental History 			

Volkswagen Jetta 1.9 TDI COMFORTLINE, 2012



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	ENGINE NUMBER	00
MODEL	JETTA	REGISTRATION NO.	HR26BR0750
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	552202
TRIM	1.9 TDI COMFORTLINE	ODOMETER READING	94294
COLOR	BLACK	INSURANCE EXPIRY	2019-4-28
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,48,291




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 8,100



Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score



8/10



6,48,291



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



IMAGES



Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score **8/10**



6,48,291

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score  **8/10**



6,48,291

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	MINOR SCRATCHES	300
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	7		0
LH FENDER	8		0
LH REAR DOOR	6	MINOR SCRATCHES	300
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	MINOR SCRATCHES	200
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	MINOR SCRATCHES	300
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	MINOR SCRATCHES	200
RH RUNNING BOARD	7		0
RH REAR DOOR	6	MINOR DENT	300
RH FRONT DOOR	7		0
RH FENDER	7		0

Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score **8/10**



6,48,291

EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7		0
ROOF (REGULAR)	8		0
PAINT CONDITION	7		0
PILLAR	2	RH SIDE PILLAR DAMAGE	3000
LH FRONT DOOR	3	NEED TO REPAIR	3500

IMAGES





 **NEED ATTENTION** 



 **DESCRIPTION**

minor scratches and minor dent all tyres already replaced

Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score

















8/10



6,48,291

IMAGES





Ordered by: vikas Madan | Inspected date: 2019-04-27

Order Id: 68237

Overall Score



8/10



6,48,291

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.