


ECO INSPECTION CERTIFICATE

Premium

Order ID : 63490

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gokam Shiv Shanker	Inspection Date : 2019-04-22	Location : SANATH NAGAR	Inspected By  Ahmed Syed Vaseem
---	--	-----------------------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **10** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

69+ vehicle inspected
1+ years experience

Audi Q5 3.0 Tdi Quattro, 2009



VEHICLE INFORMATION

MAKE	AUDI	ENGINE NUMBER	CCW069497
MODEL	Q5	REGISTRATION NO.	AP09BX4344
MFG. DATE	2009-04-23	VIN/CHASSIS NUMBER	WAUZL98R0AA051481
TRIM	3.0 TDI QUATTRO	ODOMETER READING	125050
COLOR	RED	INSURANCE EXPIRY	2016-1-8
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

16,30,851




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score **7/10**





16,30,851

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0

IMAGES



Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score **7/10**




16,30,851

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score  **7/10**



16,30,851

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0

Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score **7/10**




16,30,851

EXTERIOR (CONTINUED)


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (SUN ROOF)	7		0
PAINT CONDITION	7		0

IMAGES



DOCUMENTS



DESCRIPTION

Good condition. No major scratches.

Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score
















7/10



16,30,851

IMAGES



Ordered by: Gokam Shiv Shanker | Inspected date: 2019-04-22

Order Id: 63490

Overall Score



7/10



16,30,851

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.