


ECO INSPECTION CERTIFICATE

Premium

Order ID : 76339

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SAIREDDY NARESH	Inspection Date : 2019-05-23	Location : HYDERABAD	Inspected By  Verified Technician 79+ vehicle inspected 1+ years experience Tata Uday Kumar
---------------------------------	---------------------------------	-------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

9/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History










Volkswagen Polo 1.2 TDI HIGHLINE, 2011



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	ENGINE NUMBER	CFW090524
MODEL	POLO	REGISTRATION NO.	AP09CG1008
MFG. DATE	02/2011	VIN/CHASSIS NUMBER	WVWB11606BT035579
TRIM	1.2 TDI HIGHLINE	ODOMETER READING	78906
COLOR	WHITE	INSURANCE EXPIRY	2018-4-26
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,93,800




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 100%;"></div>	10 / 10
 Wheel	<div style="width: 90%;"></div>	9 / 10
 Test Drive	<div style="width: 100%;"></div>	10 / 10
 Exterior	<div style="width: 90%;"></div>	9 / 10
 Hood	<div style="width: 90%;"></div>	9 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score **9/10**





2,93,800

INTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	9		0
PEDALS	9		0
CENTRAL LOCK	9		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION (YES)	9		0
ODOMETER	10		0
POWER WINDOWS (YES - FRONT ONLY)	10		0
HAZARD LIGHT	9		0

IMAGES



Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score



9/10



2,93,800



TEST DRIVE




10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	10		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	9		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	9		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	9		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	9		0

 IMAGES



 HOOD



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	9		0
RADIATOR	9		0
WIRING	9		0
BATTERY	9		0
BRAKE FLUID LEVEL	9		0
ENGINE OIL	9		0
COOLANT LEVEL	9		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	9		0
EXHAUST SYSTEM	9		0

 IMAGES



Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score **9/10**



2,93,800

 **EXTERIOR**

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9		0
FRONT BUMPER	8		0
HEAD LIGHTS	9		0
GRILLE	10		0
TURN SIGNAL	9		0
FOG LAMPS	10		0
HOOD	9		0
PILLAR	9		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	10		0
LH FENDER	9		0
LH FRONT DOOR	10		0
LH REAR DOOR	10		0
LH RUNNING BOARD	9		0
LH QUARTER PANEL	9		0
FUEL LID	10		0
REAR WINDSHIELD	9		0
REAR BUMPER	10		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	9		0
LUGGAGE COMPARTMENT LIGHT	9		0
RH QUARTER PANEL	9		0
RH RUNNING BOARD	9		0
RH REAR DOOR	10		0

Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score **9/10**



2,93,800

EXTERIOR (CONTINUED)


9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES



DOCUMENTS



DESCRIPTION

good car

Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score







9/10



2,93,800

IMAGES



Ordered by: SAIREDDY NARESH | Inspected date: 2019-05-23

Order Id: 76339

Overall Score



9/10



2,93,800

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.