

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 78412

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Himanshu Car World	<b>Inspection Date :</b> 2019-05-29	<b>Location :</b> JAIPUR	<b>Inspected By</b>   <b>VICKY KUMAR</b> Verified Technician 209+ vehicle inspected 1+ years experience
---	--	-----------------------------	---

**8/10**

**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 4 Years Vehicle Age
- ✓ No Accidental History

## Toyota Fortuner 3.0 4X2 AT, 2015



VEHICLE INFORMATION			
MAKE	TOYOTA	ENGINE NUMBER	43435
MODEL	FORTUNER	REGISTRATION NO.	RJ14UD9234
MFG. DATE	04/2015	VIN/CHASSIS NUMBER	41234
TRIM	3.0 4X2 AT	ODOMETER READING	100838
COLOR	S WHITE	INSURANCE EXPIRY	2018-12-11
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

## KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	9,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

16,47,869

Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

**ECO SCORE**

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

**TOTAL ESTIMATE SPEND 0**

0

Interior

0

Wheel

0

Test Drive

0

Exterior

0

Hood

Ordered by: Himanshu car World | Inspected date: 2019-05-29

Order Id: 78412

Overall Score



8/10



16,47,869



## INTERIOR








8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	9		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	9		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	9		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	9		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	9		0
CUP HOLDERS	8		0
NAVIGATION (YES)	8		0
ODOMETER	9		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	9		0



## IMAGES





## TEST DRIVE






8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	9		0
ENGINE NOISE	8		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	9		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES



## WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	9		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES



 HOOD




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	7		0
RADIATOR	9		0
WIRING	8		0
BATTERY	9		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	7		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	7		0

 IMAGES





Ordered by: Himanshu car World | Inspected date: 2019-05-29

Order Id: 78412

Overall Score  **8/10**



**16,47,869**

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	9		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	9		0
FOG LAMPS	8		0
HOOD	9		0
PILLAR	8		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	9		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	9		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	9		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	9		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0



Ordered by: Himanshu car World | Inspected date: 2019-05-29

Order Id: 78412

Overall Score  **8/10**




**16,47,869**


## EXTERIOR (CONTINUED)

**8/10**




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	9		0
RH FENDER	7		0
BODY RUST	9		0
ROOF (REGULAR)	8		0
PAINT CONDITION	9		0

## IMAGES





 **DOCUMENTS**



 **DESCRIPTION**

good



Ordered by: Himanshu car World | Inspected date: 2019-05-29

Order Id: 78412

Overall Score




8/10



16,47,869

IMAGES









Ordered by: Himanshu car World | Inspected date: 2019-05-29

Order Id: 78412

Overall Score



8/10



16,47,869

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.