

ECO INSPECTION CERTIFICATE

Premium

Order ID : 52970

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Monika Sharma	Inspection Date : 2019-03-26	Valid Till : 2019-06-30
-------------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **116** does not need attention
- ✔ **1** Owner , **6** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

809+ vehicle inspected

2+ years experience

Santosh Kumar

Honda Civic 1.8 V AT, 2013



VEHICLE INFORMATION

MAKE	HONDA	TRANSMISSION TYPE	AUTOMATIC
MODEL	CIVIC	REGISTRATION NO.	DL13C5564
YEAR	2013	VIN/CHASIS NUMBER	500396
TRIM	1.8 V AT	KMS RUN	52808
COLOR	WHITE	INSURANCE EXPIRY	2019-5-31
BODY TYPE	SEDAN	LOCATION	GHAZIABAD
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,26,894




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10
Wheel	<div style="width: 50%; background: linear-gradient(to right, orange, gray);"></div>	5 / 10
Test Drive	<div style="width: 70%; background: linear-gradient(to right, green, gray);"></div>	7 / 10
Exterior	<div style="width: 60%; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10
Hood	<div style="width: 60%; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10

TOTAL ESTIMATE SPEND **33,850**



Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score  **6/10**




5,26,894

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	FAIR	0
PEDALS	6	FAIR	0
CENTRAL LOCK	6	FAIR	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	6	FAIR	0
HAZARD LIGHT	6	FAIR	0

IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score



6/10



5,26,894



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	FAIR	0
BRAKE PERFORMANCE	6	FAIR	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	FAIR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6	FAIR	0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0
TYRES	4	POOR	22000
SPARE TYRE (YES)	3	BAD	5500

 IMAGES



 NEED ATTENTION 



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0
ENGINE OIL	4	POOR	3500
COOLANT LEVEL	4	POOR	850

 IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score  **6/10**



5,26,894

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
HOOD	6	FAIR	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	6	PAINTED	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	MINOR PAINTED	0
LH REAR DOOR	6	FAIR	0
LH RUNNING BOARD	6	PAINTED	0
LH QUARTER PANEL	6	PAINTED	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
REAR BUMPER	6	PAINTED	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	6	PAINTED	0
RH RUNNING BOARD	6	PAINTED	0
RH REAR DOOR	6	MINOR PAINTED	0
RH FRONT DOOR	6	MINOR PAINTED	0

Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score **6/10**






5,26,894

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	PAINTED	0
BODY RUST	6	FAIR	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	6	50% PAINTED	0
FOG LAMPS	4	POOR	2000

IMAGES



NEED ATTENTION ⚠️



Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score




6/10



5,26,894

DOCUMENTS



DESCRIPTION

car is fair condition . car 50% painted need to be service need to be dryclining all tyres are ba

Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score



6/10



5,26,894

IMAGES



REGN. NO : DL13C 5564

REG. DT: 25/02/2013
 CH. NO: 1AAFC18KSCM000396
 E. NO: R18A1940207











O. S. No: 01
 MFG. CO: HONDA
 COLOUR: TARTUFA WHITE
 CLASS: L.M.V.

NAME: HONDA CARS INDIA LTD
 SWIND. OF: 1A
 ADDRESS: CROWNE PLAZA TODAY, PLOT NO-1
 COMMUNITY CENTRE, PH-1, OKHLA
 NEW DELHI 110020

MODEL: CIVIC I BV AT
 BODY: SALOON
 WHEEL BASE: 2474
 MFG. DT: 2012
 FUEL: PETROL
 REG. UPTO: 24/02/2028
 TAX UPTO: 01/11

NO. OF CYL: 4
 UNL. ASEN WT: 1240
 SEATING C: 5
 PETROL
 STANDING C: 1799
 CL. CAP: 1799

Registering Authority: Surajmal Vihar
 Signature



Ordered by: Monika Sharma | Inspected date: 2019-03-26

Order Id: 52970

Overall Score



6/10



5,26,894

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.