

ECO INSPECTION CERTIFICATE

Premium

Order ID : 79288

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : TECHNO JUSTCARS 365 PRIVATE LIMITED	Inspection Date : 2019-06-12	Location : KASTURI NAGER
---	--	------------------------------------

8/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **5** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

158+ vehicle inspected

1+ years experience

Shafiq Ulla Khan. A










Skoda Rapid 1.6 MPI ELEGANCE, 2014



VEHICLE INFORMATION

MAKE	SKODA	ENGINE NUMBER	XXXXX
MODEL	RAPID	REGISTRATION NO.	KA02MJ6512
MFG. DATE	01/2014	VIN/CHASSIS NUMBER	XXXXXX
TRIM	1.6 MPI ELEGANCE	ODOMETER READING	59322
COLOR	SILVER	INSURANCE EXPIRY	2018-6-12
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,06,972




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #28a745, #6c757d);"></div>	8 / 10
 Wheel	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #28a745, #6c757d);"></div>	8 / 10
 Test Drive	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #28a745, #6c757d);"></div>	8 / 10
 Exterior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #28a745, #6c757d);"></div>	8 / 10
 Hood	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #28a745, #6c757d);"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-06-12

Order Id: 79288

Overall Score



8/10



4,06,972



INTERIOR






8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	7		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES - FRONT ONLY)	8		0
HAZARD LIGHT	9		0



IMAGES





TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	7		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-06-12

Order Id: 79288

Overall Score



8/10



4,06,972

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	9		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	7		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-06-12

Order Id: 79288

Overall Score



8/10



4,06,972



EXTERIOR (CONTINUED)





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	9		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0



IMAGES





 **DESCRIPTION**

good

Overall Score




















8/10



4,06,972

IMAGES





Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-06-12

Order Id: 79288

Overall Score



8/10



4,06,972

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.