


ECO INSPECTION CERTIFICATE

Premium

Order ID : 69956

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Lalit Handa	Inspection Date : 2019-05-27	Location : DELHI	Inspected By  Abu Zafar Verified Technician 479+ vehicle inspected 1+ years experience
-----------------------------	---------------------------------	---------------------	--

6/10

Overall Score

- ✔ Evaluated across 6 segments
- ✔ Covered 121+ checkpoints
- ✔ 114 does not need attention
- ✔ 1 Owner , 5 Years Vehicle Age
- ✔ No Accidental History

Harley-Davidson Xg750 750CC, 2014



VEHICLE INFORMATION

MAKE	HARLEY-DAVIDSON	ENGINE NUMBER	500943
MODEL	XG750	REGISTRATION NO.	DL8SBQ2941
YEAR	2014	VIN/CHASSIS NUMBER	500943
TRIM	750CC	ODOMETER READING	4007
COLOR	BLACK	INSURANCE EXPIRY	2018-6-13
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	DUPLICATE	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,20,985




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 70%;"></div>	7 / 10
Control	<div style="width: 70%;"></div>	7 / 10
Light	<div style="width: 70%;"></div>	7 / 10
Oil	<div style="width: 40%; background-color: red;"></div>	4 / 10
Chassis	<div style="width: 70%;"></div>	7 / 10
Stand	<div style="width: 40%; background-color: red;"></div>	4 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Lalit Handa | Inspected date: 2019-05-27

Order Id: 69956

Overall Score



6/10



4,20,985



TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7		0
REAR TYRE CONDITION & AIR PRESSURE	7		0
WHEEL SPOKES FRONT	7		0
WHEEL SPOKES REAR	7		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	7		0
WHEEL BEARINGS FRONT	7		0
WHEEL BEARINGS REAR	7		0
WHEEL SEALS FRONT	7		0
WHEEL SEALS REAR	7		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

IMAGES





Ordered by: Lalit Handa | Inspected date: 2019-05-27

Order Id: 69956

Overall Score **6/10**



4,20,985

STAND


4/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE STAND CONDITION	7		0
SIDE STAND RETENTION	7		0
CENTRE STAND CONDITION	0	NA	0
CENTRE STAND RETENTION	0	NA	0

IMAGES



NEED ATTENTION ⚠




CONTROL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7		0
LEVERS & PEDAL CONDITION	7		0
PIVOTS	7		0
CABLES CONDITION	7		0

CABLES ROUTING	7		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	7		0

IMAGES




OIL



4/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7		0
LEVELS - HYDRAULIC FLUID (YES)	7		0
LEVELS - COOLANT (YES)	7		0
LEVELS - FUEL	7		0
LEAKS - ENGINE OIL	0	NA	0
LEAKS - GEAR OIL	0	NA	0
LEAKS - HYDRAULIC FLUID	0	NA	0
LEAKS - COOLANT	0	NA	0
LEAKS - FUEL	0	NA	0

IMAGES



Ordered by: Lalit Handa | Inspected date: 2019-05-27

Order Id: 69956

Overall Score **6/10**







4,20,985

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	7		0
TAILLAMP/BRAKELAMP OPERATION	7		0
TURN SIGNALS OPERATION FRONT LEFT	7		0
TURN SIGNALS OPERATION FRONT RIGHT	7		0
TURN SIGNALS OPERATION REAR LEFT	7		0
TURN SIGNALS OPERATION REAR RIGHT	7		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	7		0
MIRRORS AIM	7		0
LENSES & REFLECTORS CONDITION	7		0
WIRING CONDITION	7		0
WIRING ROUTING	7		0

IMAGES






CHASSIS

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	7		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	7		0
SUSPENSION FRONT FORKS RIGHT	7		0
SUSPENSION REAR SHOCKS LEFT	7		0
SUSPENSION REAR SHOCKS RIGHT	7		0
CHAIN/BELT TENSION	7		0
CHAIN/BELT LUBRICATION	7		0
CHAIN/BELT SPROCKETS	7		0
FASTENERS THREADED	7		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0

IMAGES



DOCUMENTS



DESCRIPTION

tire change after the 25000km

Ordered by: Lalit Handa | Inspected date: 2019-05-27

Order Id: 69956

Overall Score




6/10



4,20,985

IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by **droom**.in

Ordered by: Lalit Handa | Inspected date: 2019-05-27

Order Id: 69956

Overall Score



6/10



4,20,985

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.