

ECO INSPECTION CERTIFICATE

Premium

Order ID : 81990

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Saqib Ameen

Inspection Date :
2019-06-15

Location :
BANGALORE

8/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 1 Year Vehicle Age
- ✓ No Accidental History

Inspected By



Anand A

- ✓ Verified Technician
- 28+ vehicle inspected
- 1+ years experience






Suzuki Gixxer Sf Fi 150CC ABS, 2018



VEHICLE INFORMATION

MAKE	SUZUKI	ENGINE NUMBER	BGA1504190
MODEL	GIXXER SF FI	REGISTRATION NO.	KA03JR8294
YEAR	2018	VIN/CHASSIS NUMBER	MB8NG4BJCJ830617
TRIM	150CC ABS	ODOMETER READING	6202
COLOR	M T BLUE	INSURANCE EXPIRY	2020-5-1
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (FULL)
 TYRE LIFE REMAINING (KM)	45,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

90,799




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre	<div style="width: 80%;"></div>	8 / 10
 Control	<div style="width: 80%;"></div>	8 / 10
 Light	<div style="width: 80%;"></div>	8 / 10
 Oil	<div style="width: 80%;"></div>	8 / 10
 Chassis	<div style="width: 80%;"></div>	8 / 10
 Stand	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score



8/10



90,799

TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	7		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

IMAGES



Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score



8/10



90,799

STAND



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	7		0

IMAGES



CONTROL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	7		0

Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score **8/10**



90,799

IMAGES





OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7		0
LEVELS - HYDRAULIC FLUID (YES)	7		0
LEVELS - COOLANT (YES)	7		0
LEVELS - FUEL	8		0
LEAKS - ENGINE OIL	8		0
LEAKS - GEAR OIL	8		0
LEAKS - HYDRAULIC FLUID	8		0
LEAKS - COOLANT	8		0
LEAKS - FUEL	8		0

IMAGES



Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score



8/10



90,799

LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	7		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

IMAGES



Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score **8/10**




90,799

CHASSIS

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	7		0
SUSPENSION REAR SHOCKS RIGHT	7		0
CHAIN/BELT TENSION	7		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0

IMAGES



Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score




8/10



90,799



DOCUMENTS



DESCRIPTION

good

Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score






8/10



90,799

IMAGES



Ordered by: Saqib Ameen | Inspected date: 2019-06-15

Order Id: 81990

Overall Score



8/10



90,799

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.