

ECO INSPECTION CERTIFICATE

Premium

Order ID : 94817

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SALIMKHAN PATHAN	Inspection Date : 2019-07-19	Location : AHMEDABAD	Inspected By MUKESH PATEL
----------------------------------	---------------------------------	-------------------------	---

8/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

20+ vehicle inspected
1+ years experience

Bajaj Pulsar 150CC, 2010



VEHICLE INFORMATION

MAKE	BAJAJ	ENGINE NUMBER	M37953
MODEL	PULSAR	REGISTRATION NO.	GJ01MB7572
YEAR	2010	VIN/CHASSIS NUMBER	M46971
TRIM	150CC	ODOMETER READING	42462
COLOR	BLAK	INSURANCE EXPIRY	2019-7-19
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

20,078




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 80%;"></div>	8 / 10
Control	<div style="width: 80%;"></div>	8 / 10
Light	<div style="width: 80%;"></div>	8 / 10
Oil	<div style="width: 80%;"></div>	8 / 10
Chassis	<div style="width: 70%;"></div>	7 / 10
Stand	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 500



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score



8/10



20,078

 TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	7		0
WHEEL SPOKES FRONT	8		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	7		0
WHEEL BEARINGS FRONT	7		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	7		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

 IMAGES





Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score **8/10**



20,078

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	7		0

IMAGES




CONTROL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	7		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	8		0

IMAGES





OIL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	8		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	7		0
LEAKS - ENGINE OIL	7		0
LEAKS - GEAR OIL	7		0
LEAKS - HYDRAULIC FLUID	7		0
LEAKS - COOLANT	7		0
LEAKS - FUEL	7		0

IMAGES



Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score



8/10



20,078

 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	7		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8	NEW FITTING	500
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	7		0

 IMAGES



Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score



8/10



20,078



CHASSIS





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	7		0
SUSPENSION FRONT FORKS RIGHT	7		0
SUSPENSION REAR SHOCKS LEFT	7		0
SUSPENSION REAR SHOCKS RIGHT	7		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	7		0
CHAIN/BELT SPROCKETS	7		0
FASTENERS THREADED	7		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0



IMAGES



Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score





8/10



20,078

DOCUMENTS



DESCRIPTION

good condition

Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score













8/10



20,078

 IMAGES (27)



Ordered by: SALIMKHAN PATHAN | Inspected date: 2019-07-19

Order Id: 94817

Overall Score



8/10



20,078

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.