


ECO INSPECTION CERTIFICATE

Premium

Order ID : 96089

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Charanjit Singh	Inspection Date : 2019-07-25	Location : JAIPUR	Inspected By  VICKY KUMAR
---------------------------------	---------------------------------	----------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

301+ vehicle inspected
1+ years experience

Ford Figo 1.5D TITANIUM MT, 2010



VEHICLE INFORMATION

MAKE	FORD	ENGINE NUMBER	NOT SHOWN
MODEL	FIGO	REGISTRATION NO.	RJ14CL1870
MFG. DATE	10/2010	VIN/CHASSIS NUMBER	71445
TRIM	1.5D TITANIUM MT	ODOMETER READING	84014
COLOR	SILVER	INSURANCE EXPIRY	2019-4-14
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,42,053




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score



7/10



2,42,053



INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	8		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	7		0
NAVIGATION (YES)	6		0
ODOMETER	7		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	7		0



IMAGES



Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score **7/10**



2,42,053

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	6		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	6		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	6		0

 IMAGES





Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score  **7/10**



2,42,053

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	6		0
TURN SIGNAL	7		0
FOG LAMPS	6		0
HOOD	7		0
PILLAR	6		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	6		0
LH FRONT DOOR	7		0
LH REAR DOOR	6		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6		0
FUEL LID	8		0
REAR WINDSHIELD	7		0
REAR BUMPER	6		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	6		0

Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score



7/10



2,42,053



EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	6		0
ROOF (REGULAR)	7		0
PAINT CONDITION	6		0



IMAGES





🚗 DOCUMENTS

VVAHAN National Register e Services Ministry	
Registration No:	KH42L1K1W
Registration Date:	24/06/2019
Chassis No:	MAJ1000R2FAA****5
Engine No:	AA****5
Owner Name:	MANVIKRA SINGH SIKHARHAT
Vehicle Class:	Motor Car(LMV)
Fuel:	DIESEL
Maker / Model:	FORD INDIA PVT LTD / FORD FIGO 1.4 TITANIUM
Fitness Regn upto:	23/06/2025
Insurance upto:	23/06/2019
MV Tax upto:	PUC upto:
Emission norms:	BHARAT STAGE IV
VC Status:	ACTIVE

🚗 DESCRIPTION

good

Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score







7/10



2,42,053

IMAGES (54)







1/24 of 182

YAHYA National Register Services | Ministry

Registration No:	KU14CL1870	Registration Date:	14/06/2019
Chassis No:	MA11000R2JA000005	Engine No:	A6100005
Owner Name:	MANVIKENDRA SINGH SHEKHARAT		
Vehicle Class:	Motor Car (LMV)	Fuel:	DIESEL
Maker / Model:	FIAT INDIA PVT LTD / FIAT PUNO 1.4 TITANIUM		
Fitness Regn upto:	25-Sep-2025	Insurance upto:	28-Sep-2019
MV Tax upto:	PUC upto:		
Emission norms:	Bharat Stage IV		
RC Status:	ACTIVE		



Ordered by: Charanjit singh | Inspected date: 2019-07-25

Order Id: 96089

Overall Score



7/10



2,42,053



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.