

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 100188

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Lovendra Parashar	<b>Inspection Date :</b> 2019-08-02	<b>Location :</b> NOIDA
--	--	----------------------------

## 5/10

**Overall Score**

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **114** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

**Verified Technician**  
109+ vehicle inspected  
1+ years experience

Pradee Kumar

## Hero Passion Pro 100cc, 2010



### VEHICLE INFORMATION

<b>MAKE</b>	HERO	<b>ENGINE NUMBER</b>	53703
<b>MODEL</b>	PASSION PRO	<b>REGISTRATION NO.</b>	GJ01LP8819
<b>YEAR</b>	2010	<b>VIN/CHASSIS NUMBER</b>	18262
<b>TRIM</b>	100CC	<b>ODOMETER READING</b>	88542
<b>COLOR</b>	BLK&BLUE	<b>INSURANCE EXPIRY</b>	2019-5-30
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	12,000	<b>RC COPY AVAILABLE</b>	ORIGINAL	<b>BANK HYPOTHECATION</b>	NOT APPLICABLE
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**19,022**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Tyre</b>	<div style="width: 75%;"></div>	<b>6 / 10</b>
<b>Control</b>	<div style="width: 75%;"></div>	<b>6 / 10</b>
<b>Light</b>	<div style="width: 75%;"></div>	<b>6 / 10</b>
<b>Oil</b>	<div style="width: 30%;"></div>	<b>3 / 10</b>
<b>Chassis</b>	<div style="width: 75%;"></div>	<b>6 / 10</b>
<b>Stand</b>	<div style="width: 75%;"></div>	<b>6 / 10</b>

#### TOTAL ESTIMATE SPEND 200



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Lovendra Parashar | Inspected date: 2019-08-02

Order Id: 100188

Overall Score



5/10



19,022



## TYRE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	NEUTRAL/AVERAGE CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL SPOKES FRONT	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL SPOKES REAR	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL RIM FRONT	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL RIM REAR	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL BEARINGS FRONT	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL BEARINGS REAR	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL SEALS FRONT	6	NEUTRAL/AVERAGE CONDITION	0
WHEEL SEALS REAR	6	NEUTRAL/AVERAGE CONDITION	0
BRAKE FUNCTION FRONT	6	NEUTRAL/AVERAGE CONDITION	0
BRAKE FUNCTION REAR	6	NEUTRAL/AVERAGE CONDITION	0
BRAKES CONDITION FRONT	6	NEUTRAL/AVERAGE CONDITION	0
BRAKES CONDITION REAR	6	NEUTRAL/AVERAGE CONDITION	0

## IMAGES



Ordered by: Lovendra Parashar | Inspected date: 2019-08-02

Order Id: 100188

Overall Score  **5/10**



**19,022**

## STAND

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
CENTRE STAND RETENTION	6	NEUTRAL/AVERAGE CONDITION	0
SIDE STAND CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
SIDE STAND RETENTION	6	NEUTRAL/AVERAGE CONDITION	0

## IMAGES




## CONTROL

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
PIVOTS	6	NEUTRAL/AVERAGE CONDITION	0
CABLES CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
CABLES ROUTING	6	NEUTRAL/AVERAGE CONDITION	0
HOSES CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
HOSES ROUTING	6	NEUTRAL/AVERAGE	0

HOSES ROUTING	0	CONDITION	0
THROTTLE OPERATION	6	NEUTRAL/AVERAGE CONDITION	0

## IMAGES




## OIL

3/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	NEUTRAL/AVERAGE CONDITION	0
LEVELS - FUEL	6	NEUTRAL/AVERAGE CONDITION	0
LEAKS - ENGINE OIL	8	GOOD CONDITION	0
LEAKS - FUEL	8	GOOD CONDITION	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	0	NON-AVAILABLE/CRITICAL CONDITION	0
LEVELS - HYDRAULIC FLUID (YES)	0	NON-AVAILABLE/CRITICAL CONDITION	0
LEVELS - COOLANT (YES)	0	NON-AVAILABLE/CRITICAL CONDITION	0
LEAKS - GEAR OIL	0	NON-AVAILABLE/CRITICAL CONDITION	0
LEAKS - HYDRAULIC FLUID	0	NON-AVAILABLE/CRITICAL CONDITION	0
LEAKS - COOLANT	0	NON-AVAILABLE/CRITICAL CONDITION	0

## IMAGES



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in



Ordered by: Lovendra Parashar | Inspected date: 2019-08-02

Order Id: 100188

Overall Score  **5/10**



**19,022**

 LIGHT

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
BATTERY VENT TUBE	6	NEUTRAL/AVERAGE CONDITION	0
HEADLAMP CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	NEUTRAL/AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	6	NEUTRAL/AVERAGE CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	6	NEUTRAL/AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	6	NEUTRAL/AVERAGE CONDITION	0
SWITCHES OPERATION	6	NEUTRAL/AVERAGE CONDITION	0
MIRRORS CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
MIRRORS AIM	6	NEUTRAL/AVERAGE CONDITION	0
LENSES & REFLECTORS CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
WIRING CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
WIRING ROUTING	6	NEUTRAL/AVERAGE CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	4	MINOR DAMAGE CONDITION	200

 IMAGES










## CHASSIS

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
FRAME STEERING-HEAD BEARINGS	6	NEUTRAL/AVERAGE CONDITION	0
FRAME SWINGARM BUSHINGS	6	NEUTRAL/AVERAGE CONDITION	0
SUSPENSION FRONT FORKS LEFT	6	NEUTRAL/AVERAGE CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	NEUTRAL/AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	NEUTRAL/AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	6	NEUTRAL/AVERAGE CONDITION	0
CHAIN/BELT TENSION	6	NEUTRAL/AVERAGE CONDITION	0
CHAIN/BELT LUBRICATION	6	NEUTRAL/AVERAGE CONDITION	0
CHAIN/BELT SPROCKETS	6	NEUTRAL/AVERAGE CONDITION	0
FASTENERS THREADED	6	NEUTRAL/AVERAGE CONDITION	0
FASTENERS CLIPS & COTTER PINS	6	NEUTRAL/AVERAGE CONDITION	0
ENGINE	6	NEUTRAL/AVERAGE CONDITION	0
		NEUTRAL/AVERAGE	

 IMAGES

 DOCUMENTS

 DESCRIPTION

front mudguard broken need to Change



Ordered by: Lovendra Parashar | Inspected date: 2019-08-02

Order Id: 100188

Overall Score




5/10



19,022

IMAGES (33)



FORM 20  
Certificate of Registration

Registered No. **01-01-2023**

Detailed description of vehicle  
 A. Make of vehicle **Yamaha**  
 B. Type of vehicle **Motorcycle**  
 C. Year of registration **2023**  
 D. Condition of vehicle **New**  
 E. Registration fee **1000**  
 F. Road tax **1000**  
 G. Total amount paid **2000**  
 H. Name of the owner **Mr. Prakash Kumar**  
 I. Name of the dealer **Mr. Prakash Kumar**  
 J. Name of the dealer's address **1/1, 1st Floor, Main Road, Anantapur, Andhra Pradesh**

Date: **10/01/2023**

Signature of the Registrar

Detailed Description

1. Make of vehicle **Yamaha**  
 2. Type of vehicle **Motorcycle**  
 3. Year of registration **2023**  
 4. Condition of vehicle **New**  
 5. Registration fee **1000**  
 6. Road tax **1000**  
 7. Total amount paid **2000**  
 8. Name of the owner **Mr. Prakash Kumar**  
 9. Name of the dealer **Mr. Prakash Kumar**  
 10. Name of the dealer's address **1/1, 1st Floor, Main Road, Anantapur, Andhra Pradesh**

11. Date of expiry **31/12/23**

12. Make of motorcycle **Yamaha**  
 13. Type of motorcycle **Motorcycle**  
 14. Year of registration **2023**  
 15. Condition of motorcycle **New**  
 16. Registration fee **1000**  
 17. Road tax **1000**  
 18. Total amount paid **2000**  
 19. Name of the owner **Mr. Prakash Kumar**  
 20. Name of the dealer **Mr. Prakash Kumar**  
 21. Name of the dealer's address **1/1, 1st Floor, Main Road, Anantapur, Andhra Pradesh**

22. Date of expiry **31/12/23**



Ordered by: Lovendra Parashar | Inspected date: 2019-08-02

Order Id: 100188

Overall Score



5/10



19,022

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.