

ECO INSPECTION CERTIFICATE

Premium

Order ID : 100702

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Virender Nehra	Inspection Date : 2019-08-05	Location : BANGALOREN	Inspected By Milan Kb
--------------------------------	---------------------------------	--------------------------	------------------------------

8/10
Overall Score

- Evaluated across 6 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 1 Owner , 1 Year Vehicle Age
- No Accidental History

Verified Technician
26+ vehicle inspected
1+ years experience

Harley-Davidson Iron 883 883cc, 2018



VEHICLE INFORMATION

MAKE	HARLEY-DAVIDSON	ENGINE NUMBER	2J405399
MODEL	IRON 883	REGISTRATION NO.	KA05KM2817
YEAR	2018	VIN/CHASSIS NUMBER	G4LE2N6JN405399
TRIM	883CC	ODOMETER READING	5752
COLOR	BLACK	INSURANCE EXPIRY	2023-8-14
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

9,36,914




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 80%;"></div>	8 / 10
Control	<div style="width: 80%;"></div>	8 / 10
Light	<div style="width: 80%;"></div>	8 / 10
Oil	<div style="width: 80%;"></div>	8 / 10
Chassis	<div style="width: 80%;"></div>	8 / 10
Stand	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score



8/10



9,36,914


TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8	NEW CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	8	NEW CONDITION	0
WHEEL SPOKES FRONT	8	NEW CONDITION	0
WHEEL SPOKES REAR	8	NEW CONDITION	0
WHEEL RIM FRONT	8	NEW CONDITION	0
WHEEL RIM REAR	8	NEW CONDITION	0
WHEEL BEARINGS FRONT	8	NEW CONDITION	0
WHEEL BEARINGS REAR	8	NEW CONDITION	0
WHEEL SEALS FRONT	8	NEW CONDITION	0
WHEEL SEALS REAR	8	NEW CONDITION	0
BRAKE FUNCTION FRONT	8	NEW CONDITION	0
BRAKE FUNCTION REAR	8	NEW CONDITION	0
BRAKES CONDITION FRONT	8	NEW CONDITION	0
BRAKES CONDITION REAR	8	NEW CONDITION	0

IMAGES



Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score **8/10**



9,36,914

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	8	NEW CONDITION	0
CENTRE STAND RETENTION	8	NEW CONDITION	0
SIDE STAND CONDITION	8	NEW CONDITION	0
SIDE STAND RETENTION	8	NEW CONDITION	0

IMAGES



CONTROL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8	NEW CONDITION	0
LEVERS & PEDAL CONDITION	8	NEW CONDITION	0
PIVOTS	8	NEW CONDITION	0
CABLES CONDITION	8	NEW CONDITION	0
CABLES ROUTING	8	NEW CONDITION	0
HOSES CONDITION	8	NEW CONDITION	0
HOSES ROUTING	8	NEW CONDITION	0
THROTTLE OPERATION	8	NEW CONDITION	0

Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score **8/10**



9,36,914

IMAGES





OIL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8	NEW CONDITION	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	8	NEW CONDITION	0
LEVELS - HYDRAULIC FLUID (YES)	8	NEW CONDITION	0
LEVELS - COOLANT (YES)	8	NEW CONDITION	0
LEVELS - FUEL	8	NEW CONDITION	0
LEAKS - ENGINE OIL	8	NEW CONDITION	0
LEAKS - GEAR OIL	8	NEW CONDITION	0
LEAKS - HYDRAULIC FLUID	8	NEW CONDITION	0
LEAKS - COOLANT	8	NEW CONDITION	0
LEAKS - FUEL	8	NEW CONDITION	0

IMAGES



Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score



8/10



9,36,914



LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8	NEW CONDITION	0
BATTERY VENT TUBE	8	NEW CONDITION	0
HEADLAMP CONDITION	8	NEW CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	8	NEW CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	8	NEW CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	8	NEW CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	8	NEW CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	8	NEW CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	8	NEW CONDITION	0
SWITCHES OPERATION	8	NEW CONDITION	0
MIRRORS CONDITION	8	NEW CONDITION	0
MIRRORS AIM	8	NEW CONDITION	0
LENSES & REFLECTORS CONDITION	8	NEW CONDITION	0
WIRING CONDITION	8	NEW CONDITION	0
WIRING ROUTING	8	NEW CONDITION	0

IMAGES



Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score



8/10



9,36,914



CHASSIS



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8	NEW CONDITION	0
FRAME STEERING-HEAD BEARINGS	8	NEW CONDITION	0
FRAME SWINGARM BUSHINGS	8	NEW CONDITION	0
SUSPENSION FRONT FORKS LEFT	8	NEW CONDITION	0
SUSPENSION FRONT FORKS RIGHT	8	NEW CONDITION	0
SUSPENSION REAR SHOCKS LEFT	8	NEW CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	8	NEW CONDITION	0
CHAIN/BELT TENSION	8	NEW CONDITION	0
CHAIN/BELT LUBRICATION	8	NEW CONDITION	0
CHAIN/BELT SPROCKETS	8	NEW CONDITION	0
FASTENERS THREADED	8	NEW CONDITION	0
FASTENERS CLIPS & COTTER PINS	8	NEW CONDITION	0
ENGINE	8	NEW CONDITION	0
TRANSMISSION	8	NEW CONDITION	0



IMAGES



Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score




8/10



9,36,914



DOCUMENTS



DESCRIPTION

good

Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score






8/10



9,36,914

IMAGES (13)



Ordered by: virender nehra | Inspected date: 2019-08-05

Order Id: 100702

Overall Score



8/10



9,36,914

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.